Capital Renewal & Replacement: Detailed District School Planned Project List*

*Project scope and list may vary slightly based on actual cost at the time the work is performed and emerging system needs and priorities. DRAFT Bond Plan June 20, 2023

School	Category	Description	MCP Tier	2023 Estimated Cost
Acres Green Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	1	\$ 288,542
Acres Green Elementary	Boilers	Replace boiler(s).	1	
Acres Green Elementary	Direct Expansion Systems	Replace RTUs originally installed in 2000.		\$ 1,923,172
Arrowwood Elementary Arrowwood Elementary	Flooring	Replace original epoxy floor. Install new IP intercom system for building.	1	
Arrowwood Elementary	Boilers	Replace boiler(s).	1	
Arrowwood Elementary	Chilled Water Systems	Replace chiller.	1	\$ 576,951
Bear Canyon Elementary	Flooring	Replace VCT flooring in staff restrooms.	2	
Bear Canyon Elementary	Carpeting	Replace carpet in workrooms in stacked pods.		
Bear Canyon Elementary Bear Canyon Elementary	Switchgear Panels & Transformers	Replace main switchgear. Replace original panels and transformers.	1	\$ 192,317 \$ 211,641
Bear Canyon Elementary		Install new IP intercom system for building.	1	
Bear Canyon Elementary	Fire Alarm Systems	Upgrade fire alarm system.	1	\$ 307,734
Bear Canyon Elementary	Controls	Upgrade control system.	1	+
Buffalo Ridge Elementary Buffalo Ridge Elementary	Exterior Wall Construction Asphalt Playground	Recaulk control joints. Playpad needs resurfacing.	2	
Buffalo Ridge Elementary	Paving & Surfacing	Resurface asphalt parking lot.	2	
Buffalo Ridge Elementary		Install new IP intercom system for building.		
Buffalo Ridge Elementary	Boilers	Replace boiler(s).	1	7,
Castle Rock Elementary	Flooring	Replace VCT.	2	
Castle Rock Elementary Castle Rock Elementary	Flooring Flooring	Replace gym carpet. Replace original ceramic tile with poured acrylic.	2	
Castle Rock Elementary	Emergency Light & Power Systems	Replace generator and associated equipment.	1	
Castle Rock Elementary	Flooring	Replace ceramic tile floor with MMA.	2	
Castle Rock Elementary		Install new IP intercom system for building.		
Castle Rock Middle School	Exterior Wall Construction	Recaulk control joints.	2	
Castle Rock Middle School Castle Rock Middle School	Theater & Stage Equipment Flooring	Upgrade Strand controller. Replace kitchen flooring. Currently red hubblelite.	2	
Castle Rock Middle School		Install new IP intercom system for building.	1	
Castle Rock Middle School	Boilers	Replace boiler(s).	1	
Castle View High School	Exterior Wall Construction	Re-seal CMU, recaulk control joints.	2	
Castle View High School Castle View High School	Theater & Stage Equipment	Upgrade lighting and sound systems.	1	\$ 192,317 \$ 480,859
Castle view High School Chaparral High School	Theater & Stage Equipment	Install new IP intercom system for building. Replace cracked seats in auditorium.	2	
Chaparral High School	Sink Countertops	Replace sink counter tops in all restrooms.	2	
Chaparral High School	Exterior Wall Construction	Recaulk control joints. Re-seal CMU.		
Chaparral High School	Flooring	Replace original hubblelite floor with MMA.		
0	ŭ		2	
Chaparral High School	Theater & Stage Equipment	Upgrade lighting and sound systems.	2	\$ 192,317
Chaparral High School	Theater & Stage Equipment Intercommunication & Paging System	Install new IP intercom system for building.	2	\$ 192,317 \$ 288,542
	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring.	2	\$ 192,317 \$ 288,542 \$ 769,269
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherokee Trail Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building.	2 1 1 2 1	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherokee Trail Elementary Cherokee Trail Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system.	2 1 1 2 1 1	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherokee Trail Elementary Cherokee Trail Elementary Cherokee Trail Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace carpet.	2 1 1 2 1 1 2	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherokee Trail Elementary Cherokee Trail Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace carpet. Replace kitchen flooring.	2 1 1 2 1 1	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Carpeting Carpeting Carpeting	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace carpet. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms.	2 1 1 2 1 1 2 2 2 2 1 1 2	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,016
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherokee Trail Elementary Cherokee Trail Elementary Cherokee Trail Elementary Cherry Valley Elementary Cimarron Middle School	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace carpet. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building.	2 1 1 2 1 1 2 2 2 2 2 1 1 2	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,016 \$ 384,635
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cimarron Middle School Cimarron Middle School	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Controls	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace carpet. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade control system.	2 1 1 2 1 1 2 2 2 2 1 1 1 1	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,035 \$ 384,635 \$ 673,176
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cimarron Middle School Cimarron Middle School	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Controls Fire Alarm Systems	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace carpet. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade control system. Upgrade fire alarm system.	2 1 1 2 1 1 2 2 2 2 1 1 1 1 1 1 1 1 1 1	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,016 \$ 384,635 \$ 673,176 \$ 721,288
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cimarron Middle School Cimarron Middle School	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Controls Fire Alarm Systems Exterior Wall Construction	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace carpet. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade control system.	2 1 1 2 1 1 2 2 2 2 1 1 1 1	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,016 \$ 384,635 \$ 673,176 \$ 721,288 \$ 31,812
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cimarron Middle School Cimarron Middle School Cimarron Middle School Clear Sky Elementary Clear Sky Elementary Clear Sky Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Controls Fire Alarm Systems Exterior Wall Construction Intercommunication & Paging System Fire Alarm Systems	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade control system. Upgrade fire alarm system. Recaulk expansion joints. Reseal CMU. Install new IP intercom system for building. Upgrade fire alarm system.	2 1 1 2 1 1 2 2 2 2 1 1 1 1 2 1 1 1 2 1 1 1 1 2 1	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,016 \$ 384,635 \$ 673,176 \$ 721,288 \$ 31,812 \$ 288,542 \$ 403,958
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cimarron Middle School Cimarron Middle School Cimarron Middle School Ciear Sky Elementary Clear Sky Elementary Clear Sky Elementary Clear Sky Elementary Clear Sky Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Controls Fire Alarm Systems Exterior Wall Construction Intercommunication & Paging System Fire Alarm Systems Controls	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace carpet. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade control system. Upgrade fire alarm system. Recaulk expansion joints. Reseal CMU. Install new IP intercom system for building. Upgrade fire alarm system. Upgrade fire alarm system. Upgrade for alarm system. Upgrade control system. Upgrade control system.	2 1 1 2 1 1 2 2 2 1 1 2 1 1 1 1 2 1 1 1 2 1	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,016 \$ 384,635 \$ 673,176 \$ 721,288 \$ 31,812 \$ 288,542 \$ 403,958 \$ 740,481
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cimarron Middle School Cimarron Middle School Cimarron Middle School Ciear Sky Elementary Clear Sky Elementary Clear Sky Elementary Clear Sky Elementary Clear Sky Elementary Copper Mesa Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Controls Fire Alarm Systems Exterior Wall Construction Intercommunication & Paging System Fire Alarm Systems Controls Flooring	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace kitchen flooring. Install new IP intercom system for building. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade control system. Upgrade fire alarm system. Recaulk expansion joints. Reseal CMU. Install new IP intercom system for building. Upgrade fire alarm system. Upgrade fire alarm system. Upgrade control system. Upgrade control system. Replace VCT.	2 1 1 2 1 1 2 2 2 1 1 1 1 1 2 2 1 1 1 1	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,016 \$ 384,635 \$ 673,176 \$ 721,288 \$ 31,812 \$ 288,542 \$ 403,958 \$ 740,481 \$ 48,113
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cimarron Middle School Cimarron Middle School Cimarron Middle School Ciear Sky Elementary Clear Sky Elementary Clear Sky Elementary Clear Sky Elementary Copper Mesa Elementary Copper Mesa Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Controls Fire Alarm Systems Exterior Wall Construction Intercommunication & Paging System Fire Alarm Systems Fire Alarm Systems Controls Fire Alarm Systems Fire Controls Flooring Flooring Flooring	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace carpet. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade control system. Upgrade fire alarm system. Recaulk expansion joints. Reseal CMU. Install new IP intercom system for building. Upgrade fire alarm system. Replace vCT. Replace yCT.	2 1 1 2 1 1 2 2 2 1 1 1 1 1 2 1 1 1 1 2 2 1	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,016 \$ 384,635 \$ 673,176 \$ 721,288 \$ 31,812 \$ 288,542 \$ 403,958 \$ 740,481 \$ 48,113 \$ 77,032
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cimarron Middle School Cimarron Middle School Cimarron Middle School Ciear Sky Elementary Clear Sky Elementary Clear Sky Elementary Clear Sky Elementary Clear Sky Elementary Copper Mesa Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Controls Fire Alarm Systems Exterior Wall Construction Intercommunication & Paging System Fire Alarm Systems Controls Flooring	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace kitchen flooring. Install new IP intercom system for building. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade control system. Upgrade fire alarm system. Recaulk expansion joints. Reseal CMU. Install new IP intercom system for building. Upgrade fire alarm system. Upgrade fire alarm system. Upgrade control system. Upgrade control system. Replace VCT.	2 1 1 2 1 1 2 2 2 1 1 1 1 1 2 1 1 1 1 2 2 1	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,016 \$ 384,635 \$ 673,176 \$ 721,288 \$ 31,812 \$ 288,542 \$ 403,958 \$ 740,481 \$ 48,113 \$ 77,032
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cimarron Middle School Cimarron Middle School Cimarron Middle School Ciear Sky Elementary Clear Sky Elementary Clear Sky Elementary Clear Sky Elementary Copper Mesa Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Controls Fire Alarm Systems Exterior Wall Construction Intercommunication & Paging System Fire Alarm Systems Controls Fire Alarm Systems Controls Flooring Flooring Flooring Emergency Light & Power Systems Intercommunication & Paging System	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace carpet. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade control system. Upgrade fire alarm system. Recaulk expansion joints. Reseal CMU. Install new IP intercom system for building. Upgrade fire alarm system. Replace dere alarm system. Upgrade for alarm system. Replace ontrol system. Replace ontrol system. Replace open carpet. Replace generator and associated equipment. Install new IP intercom system for building.	2 1 1 2 1 1 2 2 2 1 1 1 1 1 2 2 1 1 1 1	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,016 \$ 384,635 \$ 673,176 \$ 721,288 \$ 31,812 \$ 288,542 \$ 403,958 \$ 740,481 \$ 48,113 \$ 77,032 \$ 144,337 \$ 288,542
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cimarron Middle School Cimarron Middle School Cimarron Middle School Ciear Sky Elementary Clear Sky Elementary Clear Sky Elementary Clear Sky Elementary Copper Mesa Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Controls Fire Alarm Systems Exterior Wall Construction Intercommunication & Paging System Fire Alarm Systems Controls Fioring Flooring Flooring Flooring Flooring Emergency Light & Power Systems Intercommunication & Paging System Carpeting	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace kitchen flooring. Install new IP intercom system for building. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade control system. Upgrade fire alarm system. Recaulk expansion joints. Reseal CMU. Install new IP intercom system for building. Upgrade fire alarm system. Upgrade fire alarm system. Upgrade control system. Replace VCT. Replace ym carpet. Replace generator and associated equipment. Install new IP intercom system for building. Replace carpet.	2 1 1 2 1 1 2 2 2 2 1 1 1 1 2 2 1 1 1 1	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,016 \$ 384,635 \$ 673,176 \$ 721,288 \$ 31,812 \$ 288,542 \$ 403,958 \$ 740,481 \$ 48,113 \$ 77,032 \$ 77,032 \$ 144,337 \$ 288,542 \$ 673,176
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cimarron Middle School Cimarron Middle School Cimarron Middle School Ciear Sky Elementary Clear Sky Elementary Clear Sky Elementary Clear Sky Elementary Copper Mesa Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Controls Fire Alarm Systems Exterior Wall Construction Intercommunication & Paging System Fire Alarm Systems Controls Flooring Flooring Flooring Flooring Emergency Light & Power Systems Intercommunication & Paging System Carpeting Flooring	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace carpet. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade control system. Upgrade fire alarm system. Recaulk expansion joints. Reseal CMU. Install new IP intercom system for building. Upgrade fire alarm system. Replace carpet in all buildings, includes modular classrooms. Replace fire alarm system. Replace fire alarm system. Replace VCT. Replace gym carpet. Replace generator and associated equipment. Install new IP intercom system for building. Replace carpet. Replace vCT in classrooms.	2 1 1 2 1 1 2 2 2 1 1 1 1 1 2 2 1 1 1 2 2 1 1 1 1 2 2 2 1 1 1 1 1 2 2 2 2 1	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,016 \$ 384,635 \$ 673,176 \$ 721,288 \$ 31,812 \$ 288,542 \$ 403,958 \$ 740,481 \$ 48,113 \$ 77,032 \$ 144,337 \$ 288,542 \$ 673,176 \$ 288,542
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cimarron Middle School Cimarron Middle School Cimarron Middle School Ciear Sky Elementary Clear Sky Elementary Clear Sky Elementary Clear Sky Elementary Copper Mesa Elementary Copper Resa Elementary Cougar Run Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Controls Fire Alarm Systems Exterior Wall Construction Intercommunication & Paging System Fire Alarm Systems Controls Flooring Flooring Flooring Emergency Light & Power Systems Intercommunication & Paging System Carpeting Flooring	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace carpet. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade control system. Upgrade fire alarm system. Recaulk expansion joints. Reseal CMU. Install new IP intercom system for building. Upgrade fire alarm system. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade fire alarm system. Replace poured system. Upgrade control system. Replace yCT. Replace gym carpet. Replace generator and associated equipment. Install new IP intercom system for building. Replace carpet. Replace carpet. Replace vCT in classrooms. Replace sheet vinyl flooring in art room.	2 1 1 1 2 2 2 2 1 1 1 1 2 1 1 1 2 2 1 1 1 1 2 2 1 1 1 1 1 2 2 1 1 1 1 2 2 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 2	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,016 \$ 384,635 \$ 673,176 \$ 721,288 \$ 31,812 \$ 288,542 \$ 403,958 \$ 740,481 \$ 48,113 \$ 77,032 \$ 77,032 \$ 144,337 \$ 288,542 \$ 288,542 \$ 31,812 \$ 288,542 \$ 31,812 \$ 288,542 \$ 31,812 \$ 403,958 \$ 740,481 \$ 48,113 \$ 77,032 \$ 77,032 \$ 77,032 \$ 144,337 \$ 288,542 \$ 21,033 \$ 21,033 \$ 24,582
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cimarron Middle School Cimarron Middle School Cimarron Middle School Ciear Sky Elementary Clear Sky Elementary Clear Sky Elementary Clear Sky Elementary Copper Mesa Elementary Cougar Run Elementary Cougar Run Elementary Cougar Run Elementary Cougar Run Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Controls Fire Alarm Systems Exterior Wall Construction Intercommunication & Paging System Fire Alarm Systems Controls Flooring Flooring Flooring Flooring Emergency Light & Power Systems Intercommunication & Paging System Carpeting Flooring	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace carpet. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade control system. Upgrade fire alarm system. Recaulk expansion joints. Reseal CMU. Install new IP intercom system for building. Upgrade fire alarm system. Replace kexpansion joints. Reseal CMU. Install new IP intercom system for building. Upgrade for alarm system. Replace generator and associated equipment. Install new IP intercom system for building. Replace generator and associated equipment. Install new IP intercom system for building. Replace carpet. Replace VCT in classrooms. Replace sheet vinyl flooring in art room. Replace sheet vinyl flooring in art room. Replace sink countertops with single surface.	2 1 1 2 1 1 2 2 2 1 1 1 1 1 2 2 1 1 1 1	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,016 \$ 384,635 \$ 673,176 \$ 721,288 \$ 31,812 \$ 288,542 \$ 403,958 \$ 740,481 \$ 48,113 \$ 77,032 \$ 144,337 \$ 288,542 \$ 673,176 \$ 21,033 \$ 24,582 \$ 38,516
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cimarron Middle School Cimarron Middle School Cimarron Middle School Ciear Sky Elementary Clear Sky Elementary Clear Sky Elementary Clear Sky Elementary Copper Mesa Elementary Cougar Run Elementary Cougar Run Elementary Cougar Run Elementary Cougar Run Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Controls Fire Alarm Systems Exterior Wall Construction Intercommunication & Paging System Fire Alarm Systems Controls Flooring	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade control system. Upgrade fire alarm system. Recaulk expansion joints. Reseal CMU. Install new IP intercom system for building. Upgrade fire alarm system. Upgrade control system. Upgrade control system. Replace VCT. Replace gym carpet. Replace generator and associated equipment. Install new IP intercom system for building. Replace carpet. Replace vCT in classrooms. Replace sheet vinyl flooring in art room. Replace Sink countertops with single surface. Replace red hubblelite floor with poured acrylic.	2 1 1 2 1 1 2 2 2 1 1 1 1 1 2 2 2 2 2 2	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,016 \$ 384,635 \$ 673,176 \$ 721,288 \$ 31,812 \$ 288,542 \$ 403,958 \$ 740,481 \$ 48,113 \$ 77,032 \$ 77,032 \$ 77,032 \$ 77,032 \$ 57,176 \$ 288,542 \$ 38,516 \$ 57,708 \$ 144,337
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cimarron Middle School Cimarron Middle School Cimarron Middle School Ciear Sky Elementary Clear Sky Elementary Clear Sky Elementary Clear Sky Elementary Copper Mesa Elementary Cougar Run Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Controls Fire Alarm Systems Exterior Wall Construction Intercommunication & Paging System Fire Alarm Systems Exterior Wall Construction Intercommunication & Paging System Fire Alarm Systems Controls Flooring Theater & Stage Equipment	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace carpet. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade control system. Upgrade fire alarm system. Recaulk expansion joints. Reseal CMU. Install new IP intercom system for building. Upgrade fire alarm system. Upgrade fire alarm system. Replace worm of building. Upgrade fire alarm system. Replace VCT. Replace gym carpet. Replace generator and associated equipment. Install new IP intercom system for building. Replace carpet. Replace vCT in classrooms. Replace sheet vinyl flooring in art room. Replace VCT. Replace sink countertops with single surface. Replace red hubblelite floor with poured acrylic. Upgrade gym sound system.	2 1 1 2 1 1 2 2 2 1 1 1 1 2 2 1 1 1 2 2 2 1 1 1 2 2 2 1 1 1 2	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,015 \$ 384,635 \$ 673,176 \$ 721,288 \$ 31,812 \$ 288,542 \$ 403,958 \$ 740,481 \$ 48,113 \$ 77,032 \$ 77,032 \$ 144,337 \$ 288,542 \$ 673,176 \$ 577,032 \$ 144,337 \$ 288,542 \$ 673,176 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7032 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cimarron Middle School Cimarron Middle School Cimarron Middle School Ciear Sky Elementary Clear Sky Elementary Clear Sky Elementary Copper Mesa Elementary Cougar Run Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Controls Fire Alarm Systems Exterior Wall Construction Intercommunication & Paging System Fire Alarm Systems Exterior Wall Construction Intercommunication & Paging System Fire Alarm Systems Controls Flooring Theater & Stage Equipment Intercommunication & Paging System	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace carpet. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade control system. Upgrade fire alarm system. Recaulk expansion joints. Reseal CMU. Install new IP intercom system for building. Upgrade fire alarm system. Replace alarm system. Upgrade control system. Replace VCT. Replace gym carpet. Replace generator and associated equipment. Install new IP intercom system for building. Replace carpet. Replace carpet. Replace sheet vinyl flooring in art room. Replace sheet vinyl flooring in art room. Replace sheet vinyl flooring in art room. Replace sink countertops with single surface. Replace red hubblelite floor with poured acrylic. Upgrade gym sound system. Install new IP intercom system for building.	2 1 1 2 1 1 2 2 2 1 1 1 1 2 2 1 1 1 2 2 2 1 1 1 2 2 1 1 1 2 2 2 2 1 1 1 2	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,016 \$ 384,635 \$ 673,176 \$ 721,288 \$ 31,812 \$ 288,542 \$ 403,958 \$ 740,481 \$ 48,113 \$ 77,032 \$ 144,337 \$ 288,542 \$ 673,176 \$ 21,033 \$ 24,582 \$ 38,516 \$ 57,708 \$ 144,337 \$ 169,313 \$ 169,313 \$ 169,313
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cimarron Middle School Cimarron Middle School Cimarron Middle School Ciear Sky Elementary Clear Sky Elementary Clear Sky Elementary Clear Sky Elementary Copper Mesa Elementary Cougar Run Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Controls Fire Alarm Systems Exterior Wall Construction Intercommunication & Paging System Fire Alarm Systems Exterior Wall Construction Intercommunication & Paging System Fire Alarm Systems Controls Flooring Theater & Stage Equipment	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace carpet. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade control system. Upgrade fire alarm system. Recaulk expansion joints. Reseal CMU. Install new IP intercom system for building. Upgrade fire alarm system. Upgrade fire alarm system. Replace worm of building. Upgrade fire alarm system. Replace VCT. Replace gym carpet. Replace generator and associated equipment. Install new IP intercom system for building. Replace carpet. Replace vCT in classrooms. Replace sheet vinyl flooring in art room. Replace VCT. Replace sink countertops with single surface. Replace red hubblelite floor with poured acrylic. Upgrade gym sound system.	2 1 1 2 1 1 2 2 2 1 1 1 1 1 2 2 1 1 1 2 2 2 1 1 1 2 2 2 1 1 1 1 2 2 2 2 1 1 1 1 2	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,015 \$ 384,635 \$ 673,176 \$ 721,288 \$ 31,812 \$ 288,542 \$ 403,958 \$ 740,481 \$ 48,113 \$ 77,032 \$ 77,032 \$ 144,337 \$ 288,542 \$ 673,176 \$ 577,032 \$ 144,337 \$ 288,542 \$ 673,176 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7032 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7032 \$ 1,7033 \$ 1,7032 \$ 1,7
Chaparral High School Chaparral High School Cherokee Trail Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cherry Valley Elementary Cimarron Middle School Cimarron Middle School Cimarron Middle School Cimarron Middle School Clear Sky Elementary Clear Sky Elementary Clear Sky Elementary Clear Sky Elementary Copper Mesa Elementary Cougar Run Elementary	Theater & Stage Equipment Intercommunication & Paging System Boilers Flooring Intercommunication & Paging System Controls Carpeting Flooring Intercommunication & Paging System Controls Carpeting Intercommunication & Paging System Carpeting Intercommunication & Paging System Controls Fire Alarm Systems Exterior Wall Construction Intercommunication & Paging System Fire Alarm Systems Controls Flooring Flooring Flooring Flooring Emergency Light & Power Systems Intercommunication & Paging System Carpeting Flooring Theater & Stage Equipment Intercommunication & Paging System Boilers	Install new IP intercom system for building. Replace boiler(s). Replace kitchen flooring. Install new IP intercom system for building. Upgrade control system. Replace carpet. Replace kitchen flooring. Install new IP intercom system for building. Replace carpet in all buildings, includes modular classrooms. Install new IP intercom system for building. Upgrade control system. Upgrade fire alarm system. Recaulk expansion joints. Reseal CMU. Install new IP intercom system for building. Upgrade fire alarm system. Upgrade fire alarm system. Replace alarm system. Upgrade control system. Replace yCT. Replace gym carpet. Replace gym carpet. Replace generator and associated equipment. Install new IP intercom system for building. Replace carpet. Replace sheet vinyl flooring in all restrooms. Replace sheet vinyl flooring in art room. Replace sheet vinyl flooring in art room. Replace sink countertops with single surface. Replace red hubblelite floor with poured acrylic. Upgrade gym sound system. Install new IP intercom system for building. Replace boiler(s).	2 1 1 2 1 1 2 2 2 1 1 1 1 1 2 2 2 2 2 2	\$ 192,317 \$ 288,542 \$ 769,269 \$ 144,337 \$ 288,542 \$ 576,951 \$ 673,176 \$ 38,516 \$ 96,224 \$ 176,016 \$ 384,635 \$ 673,176 \$ 721,288 \$ 721,288 \$ 31,812 \$ 288,542 \$ 403,958 \$ 740,481 \$ 48,113 \$ 77,032 \$ 77,032 \$ 673,176 \$ 31,812 \$ 288,542 \$ 403,958 \$ 740,481 \$ 48,113 \$ 77,032 \$ 77,032 \$ 57,032 \$ 673,176 \$ 144,337 \$ 288,542 \$ 673,176 \$ 144,337 \$ 288,542 \$ 673,176 \$ 144,337 \$ 288,542 \$ 38,516 \$ 57,708 \$ 144,337 \$ 24,582 \$ 38,516 \$ 57,708 \$ 144,337 \$ 288,542

	T			_	
Coyote Creek Elementary	Panels & Transformers	Replace original panels and transformers.		\$	192,317
Coyote Creek Elementary		Install new IP intercom system for building.		\$	288,542
Coyote Creek Elementary	Fire Alarm Systems	Upgrade fire alarm system.		\$	307,734
Coyote Creek Elementary	Controls	Upgrade control system.		\$	576,951
Coyote Creek Elementary	Carpeting	Replace carpet.		\$	673,176
Cresthill Middle School	Flooring	Replace kitchen flooring, original poured acrylic.		\$	144,337
Cresthill Middle School	Panels & Transformers	Replace original panels and transformers.	1	\$	211,641
Cresthill Middle School	Intercommunication & Paging System	Install new IP intercom system for building.	1	\$	384,635
Cresthill Middle School	Fire Alarm Systems	Upgrade fire alarm system.	1	\$	673,176
Cresthill Middle School	Controls	Upgrade control system.	1	\$	1,153,903
Cresthill Middle School	Carpeting	Replace carpet.	2	\$	1,442,445
DC Oakes High School	Terminal Self-Contained Units	Replace condensing units.	1	\$	144,337
DC Oakes High School	Intercommunication & Paging System	Install new IP intercom system for building.	1	\$	144,337
DC Oakes High School	Emergency Light & Power Systems	Replace generator and associated equipment.	1	\$	144,337
DC Oakes High School	Carpeting	Replace carpet.		\$	288,542
Douglas County High School	Theater & Stage Equipment	South 100A Stage/Dance, replace damaged curtain and track		\$	35,755
Douglas County High School	Flooring	Replace ceramic tile flooring in two sets of restrooms at 2 story		\$	38,516
Douglas County High School	Emergency Light & Power Systems	Replace generator and associated equipment.	1		144,337
Douglas County High School	Theater & Stage Equipment	Auditorium theatrical equipment old and not comparable with other	2	_	169,313
Douglas County High School	Theater & Stage Equipment Theater & Stage Equipment	Upgrade lighting and sound systems.		\$	192,317
Douglas County High School		Install new IP intercom system for building.		\$	384,635
Douglas County High School	Flooring	South 104B Office, 50, 50B, 53B, 66A remove and replace VCT		\$	15,906
Douglas County High School	Flooring	Replace poured acrylic flooring in all south building restrooms.	2		96,224
Douglas County High School	0 0 3	Install new IP intercom system for south building.		\$	384,635
Eagle Ridge Elementary	Flooring	Replace epoxy floor with MMA.		\$	144,337
Eagle Ridge Elementary	· · · · · · · · · · · · · · · · · · ·	Install new IP intercom system for building.		\$	288,542
Early Childhood Center-CR		Install new IP intercom system for building.		\$	144,337
Early Childhood Center-CR	Fire Alarm Systems	Upgrade fire alarm system.	1	-	230,834
Eldorado Elementary	Flooring	Replace VCT in classrooms.	2		15,906
Eldorado Elementary	Sink Countertops	Replace sink countertops with single surface.		\$	57,708
Eldorado Elementary	Flooring	Replace sheet vinyl flooring with MMA.		\$	77,032
Eldorado Elementary	Flooring	Replace kitchen floor.	2	\$	144,337
Eldorado Elementary	Chilled Water Systems	Replace cooling tower.	1		240,429
Eldorado Elementary		Install new IP intercom system for building.	1		288,542
Flagstone Elementary	Exterior Wall Construction	Recaulk building control joints. Seal CMU.		\$	31,812
Flagstone Elementary	Emergency Light & Power Systems	Replace generator and associated equipment.		\$	144,337
Flagstone Elementary	Chilled Water Systems	Replace cooling tower.		\$	240,429
			1		288,542
Flagstone Elementary		Install new IP intercom system for building.		_	
Flagstone Elementary	Chilled Water Systems	Upgrade chiller.		\$	576,951
Flagstone Elementary	Carpeting	Replace carpet.		\$	673,176
Fox Creek Elementary	Flooring	Replace VCT in classrooms.		\$	57,445
Fox Creek Elementary	Flooring	Replace kitchen flooring with MMA.		\$	144,337
Fox Creek Elementary	Switchgear	Replace main switchgear.	1	-	192,317
Fox Creek Elementary	Panels & Transformers	Replace original panels and transformers.		\$	192,317
Fox Creek Elementary		Install new IP intercom system for building.		\$	288,542
Fox Creek Elementary	Fire Alarm Systems	Upgrade fire alarm system.	1	\$	307,734
Fox Creek Elementary	Controls	Upgrade control system.	1	\$	576,951
Franktown Elementary	Wash Fountains	Replace trough washing stations with sinks (6).	2	\$	33,915
Franktown Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	1	\$	288,542
Frontier Valley Elementary	Sink Countertops	Replace sink countertops with single surface.	2	\$	57,708
Frontier Valley Elementary	Flooring	Replace sheet vinyl flooring with MMA.	2	\$	77,032
Frontier Valley Elementary	Chilled Water Systems	Replace cooling tower.	1		240,429
Frontier Valley Elementary		Install new IP intercom system for building.		\$	288,542
Gold Rush Elementary	Exterior Wall Construction	Repair flashing on east side front entry.	2	\$	3,286
Gold Rush Elementary	Exterior Wall Construction	Recaulk expansion joints. Reseal CMU.		\$	31,812
Gold Rush Elementary		Install new IP intercom system for building.		\$	288,542
Gold Rush Elementary	Fire Alarm Systems	Upgrade fire alarm system.		\$	403,958
Gold Rush Elementary	Controls	Upgrade control system.		\$	740,481
Heritage Elementary	Flooring	Replace VCT.		\$	43,774
,				\$	131,191
Heritage Elementary	Flooring	Replace poured acrylic kitchen flooring.			288,542
Heritage Elementary		Install new IP intercom system for building.		\$	
Highlands Ranch High School		Replace sheet vinyl with MMA 4 student restrooms, coat tile		\$	77,032
Highlands Ranch High School	Theater & Stage Equipment	Replace auditorium seating.		\$	126,985
Highlands Ranch High School	Flooring	Replace kitchen flooring.		\$	144,337
Highlands Ranch High School	Theater & Stage Equipment	Upgrade lighting and sound systems.		\$	192,317
Highlands Ranch High School		Install new IP intercom system for building.		\$	480,859
Highlands Ranch High School		Replace VCT.		\$	2,284,802
Highlands Ranch High School	Paving & Surfacing	Resurface asphalt parking lot.		\$	2,884,758
Iron Horse Elementary	Flooring	Replace main hallway restrooms with poured acrylic. Pod restrooms		\$	16,957
Iron Horse Elementary	Hot Water Distribution	DHW heater needs replaced.		\$	36,282
Iron Horse Elementary	Sink Countertops	Replace sink countertops with single surface.	2	\$	57,708
Iron Horse Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	1	\$	288,542
Iron Horse Elementary	Boilers	Replace boiler(s).		\$	480,859
Larkspur Elementary	Wash Fountains	Replace trough washing stations with sinks (2).		\$	11,436
Larkspur Elementary	Flooring	Replace ceramic tile with MMA.		\$	77,032
Larkspur Elementary	Switchgear	Replace main switchgear.		\$	192,317
Larkspur Elementary	Panels & Transformers	Replace panels and transformers not yet replaced.		\$	192,317
	Boilers	Replace boiler(s).		\$	288,542
Larksnur Flementary		replace belief (3).			,
Larkspur Elementary		Install new IP intercom system for building	4	2.	788 547
Larkspur Elementary	Intercommunication & Paging System	Install new IP intercom system for building. Resurface asphalt parking lot		\$	288,542 1 923 172
		Install new IP intercom system for building. Resurface asphalt parking lot. Replace roof.	2	\$ \$	288,542 1,923,172 2,884,758

Legacy Point Elementary Flooring Replace VCT. 2 \$ Legacy Point Elementary Flooring Replace gym carpet with sport flooring. 2 \$ Legacy Point Elementary Chilled Water Systems Replace coloning tower. 1 \$ Legacy Point Elementary Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Legacy Point Elementary Flooring Replace coloning tower. 2 \$ Legacy Point Elementary Flooring Replace coloning tower. 1 \$ Legend High School Exterior Wall Construction Repair moisture penetration at F pod entrance. 2 \$ Legend High School Theater & Stage Equipment Upgrade lighting and sound systems. 2 \$ Legend High School Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Legend High School Fire Alarm Systems Upgrade fire alarm system. 1 \$ Legend High School Controls Upgrade control system. 1 \$ Legend High School Controls Upgrade control system. 1 \$ Legend High School Controls Upgrade control system.	38,516 77,032 144,337 240,429 288,542 673,176 10,648 192,317 480,859 673,176 2,009,800 4,338 31,812 57,708 269,349 288,542 634,660 961,586 31,812 134,740 250,025 288,542 27,748 288,542 288,542 31,81
Legacy Point Elementary Emergency Light & Power Systems Replace generator and associated equipment. 1 \$ Legacy Point Elementary Chilled Water Systems Replace cooling tower. 1 \$ Legacy Point Elementary Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Legend High School Exterior Wall Construction Repair moisture penetration at F pod entrance. 2 \$ Legend High School Intercommunication & Paging System Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Legend High School Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Legend High School Fire Alarm Systems Upgrade fire alarm system. 1 \$ Legend High School Controls Upgrade control system. 1 \$ Legend High School Controls Upgrade fire alarm system. 1 \$ Legend High School Controls Upgrade control system. 1 \$ Lone Tree Elementary Flooring Repair VCT at cafeteria entrance. 2 \$	144,337 240,429 288,542 673,176 10,648 192,317 480,859 673,176 2,009,800 4,338 31,812 57,708 269,349 288,542 634,660 961,586 31,812 134,740 250,025 288,542 403,958
Legacy Point Elementary Chilled Water Systems Replace cooling tower. 1 \$ Legacy Point Elementary Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Legach High School Exterior Wall Construction Repair moisture penetration at F pod entrance. 2 \$ Legend High School Theater & Stage Equipment Upgrade lighting and sound systems. 2 \$ Legend High School Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Legend High School Fire Alarm Systems Upgrade control system. 1 \$ Legend High School Controls Upgrade control system. 1 \$ Legend High School Controls Upgrade control system. 1 \$ Legend High School Controls Upgrade control system. 1 \$ Legend High School Controls Upgrade control system. 1 \$ Legend High School Controls Upgrade control system. 1 \$ Lone Tree Elementary Exterior Wall Construction Recall kontrol joints. Seal masonry CMU. 2 \$	240,429 288,542 673,176 10,648 192,317 480,859 673,176 2,009,800 4,338 31,812 269,349 288,542 634,660 961,586 31,812 134,740 250,025 288,542 403,958
Legacy Point Elementary Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Legacy Point Elementary Flooring Replace carpet. 2 \$ Legend High School Exterior Wall Construction Repair moisture penetration at F pod entrance. 2 \$ Legend High School Intercommunication & Paging System Upgrade lighting and sound systems. 2 \$ Legend High School Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Legend High School Fire Alarm Systems Upgrade fire alarm system. 1 \$ Legend High School Controls Upgrade fire alarm system. 1 \$ Legend High School Controls Upgrade fire alarm system. 1 \$ Legend High School Controls Upgrade fire alarm system. 1 \$ Legend High School Controls Upgrade fire alarm system. 1 \$ Legend High School Exterior Wall Construction Repale control system. 2 \$ Lone Tree Elementary Sink Countertops Replace sink counter tops in all restrooms. 2 \$ <td>288,542 673,176 10,648 192,317 480,859 673,176 2,009,800 4,338 31,812 57,708 269,349 288,542 634,660 961,586 31,812 134,740 250,025 288,542 403,958</td>	288,542 673,176 10,648 192,317 480,859 673,176 2,009,800 4,338 31,812 57,708 269,349 288,542 634,660 961,586 31,812 134,740 250,025 288,542 403,958
Legacy Point ElementaryFlooringReplace carpet.2\$Legend High SchoolExterior Wall ConstructionRepair moisture penetration at F pod entrance.2\$Legend High SchoolTheater & Stage EquipmentUpgrade lighting and sound systems.2\$Legend High SchoolIntercommunication & Paging SystemInstall new IP intercom system for building.1\$Legend High SchoolFire Alarm SystemsUpgrade fire alarm system.1\$Legend High SchoolControlsUpgrade control system.1\$Lone Tree ElementaryFlooringRepair VCT at cafeteria entrance.2\$Lone Tree ElementaryExterior Wall ConstructionRecaulk control joints. Seal masonry CMU.2\$Lone Tree ElementarySink CountertopsReplace sink counter tops in all restrooms.2\$Lone Tree ElementaryFire Alarm SystemsUpgrade fire alarm system.1\$Lone Tree ElementaryIntercommunication & Paging SystemInstall new IP intercom system for building.1\$Lone Tree ElementaryControlsUpgrade control system.1\$Lone Tree ElementaryRoof FinishesReplace .045 EDPM ballasted roof with .060 EDPM fully adhered.1\$Mammoth Heights ElementaryExterior Wall ConstructionRecaulk expansion joints. Reseal CMU.2\$Mammoth Heights ElementaryPaving & SurfacingResurface asphalt playground.2\$Mammoth Heights ElementaryPaving & SurfacingResurface	673,176 10,648 192,317 480,859 673,176 2,009,800 4,338 31,812 57,708 269,349 288,542 634,660 961,586 31,812 134,740 250,025 288,542 403,958
Legend High SchoolExterior Wall ConstructionRepair moisture penetration at F pod entrance.2 \$Legend High SchoolTheater & Stage EquipmentUpgrade lighting and sound systems.2 \$Legend High SchoolIntercommunication & Paging SystemInstall new IP intercom system for building.1 \$Legend High SchoolFire Alarm SystemsUpgrade fire alarm system.1 \$Legend High SchoolControlsUpgrade control system.1 \$Lone Tree ElementaryFlooringRepair VCT at cafeteria entrance.2 \$Lone Tree ElementaryExterior Wall ConstructionRecaulk control joints. Seal masonry CMU.2 \$Lone Tree ElementarySink CountertopsReplace sink counter tops in all restrooms.2 \$Lone Tree ElementaryFire Alarm SystemsUpgrade fire alarm system.1 \$Lone Tree ElementaryIntercommunication & Paging SystemInstall new IP intercom system for building.1 \$Lone Tree ElementaryControlsUpgrade control system.1 \$Lone Tree ElementaryRoof FinishesReplace .045 EDPM ballasted roof with .060 EDPM fully adhered.1 \$Mammoth Heights ElementaryPaving & SurfacingResurface asphalt payground.2 \$Mammoth Heights ElementaryPaving & SurfacingResurface asphalt parking lot.2 \$Mammoth Heights ElementaryIntercommunication & Paging SystemInstall new IP intercom system.1 \$Mammoth Heights ElementaryIntercommunication & Paging SystemUpgrade fire alarm system.1 \$Mammoth Heights Elementary <td>10,648 192,317 480,859 2,009,800 4,338 31,812 57,708 269,349 288,542 634,660 961,586 31,812 134,740 250,025 288,542 403,958</td>	10,648 192,317 480,859 2,009,800 4,338 31,812 57,708 269,349 288,542 634,660 961,586 31,812 134,740 250,025 288,542 403,958
Legend High SchoolTheater & Stage EquipmentUpgrade lighting and sound systems.2 \$Legend High SchoolIntercommunication & Paging SystemInstall new IP intercom system for building.1 \$Legend High SchoolFire Alarm SystemsUpgrade fire alarm system.1 \$Legend High SchoolControlsUpgrade control system.1 \$Lone Tree ElementaryFlooringRepair VCT at cafeteria entrance.2 \$Lone Tree ElementaryExterior Wall ConstructionRecaulk control joints. Seal masonry CMU.2 \$Lone Tree ElementarySink CountertopsReplace sink counter tops in all restrooms.2 \$Lone Tree ElementaryFire Alarm SystemsUpgrade fire alarm system.1 \$Lone Tree ElementaryIntercommunication & Paging SystemIntercom system for building.1 \$Lone Tree ElementaryControlsUpgrade control system.1 \$Lone Tree ElementaryRoof FinishesReplace .045 EDPM ballasted roof with .060 EDPM fully adhered.1 \$Mammoth Heights ElementaryResurface asphalt parking lot.2 \$Mammoth Heights ElementaryPaving & SurfacingResurface asphalt parking lot.2 \$Mammoth Heights ElementaryIntercommunication & Paging SystemInstall new IP intercom system for building.1 \$Mammoth Heights ElementaryPaving & SurfacingResurface asphalt parking lot.2 \$Mammoth Heights ElementaryIntercommunication & Paging System1 \$Meadow View ElementaryAsphalt PlaygroundReplace playground asphalt parking lot.2	192,317 480,859 673,176 2,009,800 4,338 31,812 57,708 269,349 288,542 634,660 961,586 31,812 134,740 250,025 288,542 403,958
Legend High SchoolIntercommunication & Paging SystemInstall new IP intercom system for building.1Legend High SchoolFire Alarm SystemsUpgrade fire alarm system.1Legend High SchoolControlsUpgrade control system.1Lone Tree ElementaryFlooringRepair VCT at cafeteria entrance.2Lone Tree ElementaryExterior Wall ConstructionRecaulk control joints. Seal masonry CMU.2Lone Tree ElementarySink CountertopsReplace sink counter tops in all restrooms.2Lone Tree ElementaryFire Alarm SystemsUpgrade fire alarm system.1Lone Tree ElementaryIntercommunication & Paging SystemInstall new IP intercom system for building.1Lone Tree ElementaryControlsUpgrade control system.1Lone Tree ElementaryRoof FinishesReplace .045 EDPM ballasted roof with .060 EDPM fully adhered.1Lone Tree ElementaryExterior Wall ConstructionRecaulk expansion joints. Reseal CMU.2Mammoth Heights ElementaryAsphalt PlaygroundResurface asphalt playground.2Mammoth Heights ElementaryPaving & SurfacingResurface asphalt parking lot.2Mammoth Heights ElementaryIntercommunication & Paging SystemInstall new IP intercom system for building.1Mammoth Heights ElementaryIntercommunication & Paging System1\$Mammoth Heights ElementaryFire Alarm SystemsUpgrade fire alarm system.1\$Mammoth Heights ElementaryAsphalt PlaygroundReplace playgro	480,859 673,176 2,009,800 4,338 31,812 57,708 269,349 288,542 634,660 961,586 31,812 134,740 250,025 288,542 403,958
Legend High SchoolFire Alarm SystemsUpgrade fire alarm system.1Legend High SchoolControlsUpgrade control system.1Lone Tree ElementaryFlooringRepair VCT at cafeteria entrance.2Lone Tree ElementaryExterior Wall ConstructionRecaulk control joints. Seal masonry CMU.2Lone Tree ElementarySink CountertopsReplace sink counter tops in all restrooms.2Lone Tree ElementaryFire Alarm SystemsUpgrade fire alarm system.1Lone Tree ElementaryIntercommunication & Paging SystemInstall new IP intercom system for building.1Lone Tree ElementaryControlsUpgrade control system.1Lone Tree ElementaryRoof FinishesReplace .045 EDPM ballasted roof with .060 EDPM fully adhered.1Lone Tree ElementaryRecoulk expansion joints. Reseal CMU.2Mammoth Heights ElementaryAsphalt PlaygroundResurface asphalt playground.2Mammoth Heights ElementaryPaving & SurfacingResurface asphalt parking lot.2Mammoth Heights ElementaryIntercommunication & Paging SystemInstall new IP intercom system for building.1Mammoth Heights ElementaryFire Alarm SystemsUpgrade fire alarm system.1Mammoth Heights ElementaryFire Alarm SystemsUpgrade fire alarm system.1Meadow View ElementaryControlsUpgrade control system.1Meadow View ElementaryChilled Water SystemsReplace playground asphalt play pad.2Meadow View Elementary	673,176 2,009,800 4,338 31,812 57,708 269,349 288,542 634,660 961,586 31,812 134,740 250,025 288,542 403,958
Legend High SchoolControlsUpgrade control system.1Lone Tree ElementaryFlooringRepair VCT at cafeteria entrance.2Lone Tree ElementaryExterior Wall ConstructionRecaulk control joints. Seal masonry CMU.2Lone Tree ElementarySink CountertopsReplace sink counter tops in all restrooms.2Lone Tree ElementaryFire Alarm SystemsUpgrade fire alarm system.1Lone Tree ElementaryIntercommunication & Paging SystemInstall new IP intercom system for building.1Lone Tree ElementaryControlsUpgrade control system.1Lone Tree ElementaryRoof FinishesReplace .045 EDPM ballasted roof with .060 EDPM fully adhered.1Mammoth Heights ElementaryExterior Wall ConstructionRecaulk expansion joints. Reseal CMU.2Mammoth Heights ElementaryPaving & SurfacingResurface asphalt playground.2Mammoth Heights ElementaryPaving & SurfacingResurface asphalt parking lot.2Mammoth Heights ElementaryIntercommunication & Paging SystemInstall new IP intercom system for building.1Mammoth Heights ElementaryFire Alarm SystemsUpgrade fire alarm system.1Meadow View ElementaryControlsUpgrade control systems.1Meadow View ElementaryChilled Water SystemsReplace playground asphalt play pad.2Meadow View ElementaryPaving & SurfacingResurface asphalt parking lot.2	2,009,800 4,338 31,812 57,708 269,349 288,542 634,660 961,586 31,812 134,740 250,025 288,542 403,958
Lone Tree Elementary Flooring Repair VCT at cafeteria entrance. 2 \$ Lone Tree Elementary Exterior Wall Construction Recaulk control joints. Seal masonry CMU. 2 \$ Lone Tree Elementary Sink Countertops Replace sink counter tops in all restrooms. 2 \$ Lone Tree Elementary Fire Alarm Systems Upgrade fire alarm system. 1 \$ Lone Tree Elementary Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Lone Tree Elementary Controls Upgrade control system. 1 \$ Lone Tree Elementary Roof Finishes Replace .045 EDPM ballasted roof with .060 EDPM fully adhered. 1 \$ Mammoth Heights Elementary Exterior Wall Construction Recaulk expansion joints. Reseal CMU. 2 \$ Mammoth Heights Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$ Mammoth Heights Elementary Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Mammoth Heights Elementary Fire Alarm Systems Upgrade fire alarm system. 1 \$ Mammoth Heights Elementary Fire Alarm Systems Upgrade control system. 1 \$ Mammoth Heights Elementary Controls Upgrade control system. 1 \$ Meadow View Elementary Chilled Water Systems Replace cooling tower. 1 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$	4,338 31,812 57,708 269,349 288,542 634,660 961,586 31,812 134,740 250,025 288,542 403,958
Lone Tree Elementary Exterior Wall Construction Recaulk control joints. Seal masonry CMU. Lone Tree Elementary Sink Countertops Replace sink counter tops in all restrooms. Lone Tree Elementary Fire Alarm Systems Upgrade fire alarm system. Lone Tree Elementary Intercommunication & Paging System Install new IP intercom system for building. Lone Tree Elementary Controls Upgrade control system. Lone Tree Elementary Roof Finishes Replace .045 EDPM ballasted roof with .060 EDPM fully adhered. 1 \$ Mammoth Heights Elementary Exterior Wall Construction Recaulk expansion joints. Reseal CMU. 2 \$ Mammoth Heights Elementary Asphalt Playground Resurface asphalt playground. 2 \$ Mammoth Heights Elementary Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Mammoth Heights Elementary Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Mammoth Heights Elementary Fire Alarm Systems Upgrade fire alarm system. 1 \$ Mammoth Heights Elementary Controls Upgrade control system. 1 \$ Mammoth Heights Elementary Asphalt Playground Replace playground asphalt play pad. 2 \$ Meadow View Elementary Chilled Water Systems Replace cooling tower. 1 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot.	31,812 57,708 269,349 288,542 634,660 961,586 31,812 134,740 250,025 288,542 403,958
Lone Tree Elementary Sink Countertops Replace sink counter tops in all restrooms. 2 \$ Lone Tree Elementary Fire Alarm Systems Upgrade fire alarm system. 1 \$ Lone Tree Elementary Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Lone Tree Elementary Controls Upgrade control system. 1 \$ Lone Tree Elementary Roof Finishes Replace .045 EDPM ballasted roof with .060 EDPM fully adhered. 1 \$ Mammoth Heights Elementary Exterior Wall Construction Recaulk expansion joints. Reseal CMU. 2 \$ Mammoth Heights Elementary Asphalt Playground Resurface asphalt playground. 2 \$ Mammoth Heights Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$ Mammoth Heights Elementary Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Mammoth Heights Elementary Fire Alarm Systems Upgrade fire alarm system. 1 \$ Mammoth Heights Elementary Asphalt Playground Replace playground asphalt play pad. 2 \$ Meadow View Elementary Asphalt Playground Replace playground asphalt play pad. 2 \$ Meadow View Elementary Chilled Water Systems Replace cooling tower. 1 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$ Meadow View Elementary Pavi	57,708 269,349 288,542 634,660 961,586 31,812 134,740 250,025 288,542 403,958
Lone Tree ElementarySink CountertopsReplace sink counter tops in all restrooms.2 \$Lone Tree ElementaryFire Alarm SystemsUpgrade fire alarm system.1 \$Lone Tree ElementaryIntercommunication & Paging SystemInstall new IP intercom system for building.1 \$Lone Tree ElementaryControlsUpgrade control system.1 \$Lone Tree ElementaryRoof FinishesReplace .045 EDPM ballasted roof with .060 EDPM fully adhered.1 \$Mammoth Heights ElementaryExterior Wall ConstructionRecaulk expansion joints. Reseal CMU.2 \$Mammoth Heights ElementaryAsphalt PlaygroundResurface asphalt playground.2 \$Mammoth Heights ElementaryPaving & SurfacingResurface asphalt parking lot.2 \$Mammoth Heights ElementaryIntercommunication & Paging SystemInstall new IP intercom system for building.1 \$Mammoth Heights ElementaryFire Alarm SystemsUpgrade fire alarm system.1 \$Mammoth Heights ElementaryFire Alarm SystemsUpgrade control system.1 \$Meadow View ElementaryAsphalt PlaygroundReplace playground asphalt play pad.2 \$Meadow View ElementaryChilled Water SystemsReplace cooling tower.1 \$Meadow View ElementaryPaving & SurfacingResurface asphalt parking lot.2 \$	269,349 288,542 634,660 961,586 31,812 134,740 250,025 288,542 403,958
Lone Tree Elementary Fire Alarm Systems Upgrade fire alarm system. 1 \$ Lone Tree Elementary Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Lone Tree Elementary Controls Upgrade control system. 1 \$ Lone Tree Elementary Roof Finishes Replace .045 EDPM ballasted roof with .060 EDPM fully adhered. 1 \$ Mammoth Heights Elementary Exterior Wall Construction Recaulk expansion joints. Reseal CMU. 2 \$ Mammoth Heights Elementary Asphalt Playground Resurface asphalt playground. 2 \$ Mammoth Heights Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$ Mammoth Heights Elementary Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Mammoth Heights Elementary Fire Alarm Systems Upgrade fire alarm system. 1 \$ Mammoth Heights Elementary Controls Upgrade control system. 1 \$ Meadow View Elementary Asphalt Playground Replace playground asphalt play pad. 2 \$ Meadow View Elementary Chilled Water Systems Replace cooling tower. 1 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$	269,349 288,542 634,660 961,586 31,812 134,740 250,025 288,542 403,958
Lone Tree Elementary Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Lone Tree Elementary Controls Upgrade control system. 1 \$ Lone Tree Elementary Roof Finishes Replace .045 EDPM ballasted roof with .060 EDPM fully adhered. 1 \$ Mammoth Heights Elementary Exterior Wall Construction Recaulk expansion joints. Reseal CMU. 2 \$ Mammoth Heights Elementary Asphalt Playground Resurface asphalt playground. 2 \$ Mammoth Heights Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$ Mammoth Heights Elementary Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Mammoth Heights Elementary Fire Alarm Systems Upgrade fire alarm system. 1 \$ Mammoth Heights Elementary Controls Upgrade control system. 1 \$ Meadow View Elementary Asphalt Playground Replace playground asphalt play pad. 2 \$ Meadow View Elementary Chilled Water Systems Replace cooling tower. 1 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$	288,542 634,660 961,586 31,812 134,740 250,025 288,542 403,958
Lone Tree ElementaryControlsUpgrade control system.1Lone Tree ElementaryRoof FinishesReplace .045 EDPM ballasted roof with .060 EDPM fully adhered.1Mammoth Heights ElementaryExterior Wall ConstructionRecaulk expansion joints. Reseal CMU.2Mammoth Heights ElementaryAsphalt PlaygroundResurface asphalt playground.2Mammoth Heights ElementaryPaving & SurfacingResurface asphalt parking lot.2Mammoth Heights ElementaryIntercommunication & Paging System Install new IP intercom system for building.1Mammoth Heights ElementaryFire Alarm SystemsUpgrade fire alarm system.1Mammoth Heights ElementaryControlsUpgrade control system.1Meadow View ElementaryAsphalt PlaygroundReplace playground asphalt play pad.2Meadow View ElementaryChilled Water SystemsReplace cooling tower.1Meadow View ElementaryPaving & SurfacingResurface asphalt parking lot.2	634,660 961,586 31,812 134,740 250,025 288,542 403,958
Lone Tree ElementaryRoof FinishesReplace .045 EDPM ballasted roof with .060 EDPM fully adhered.1 \$Mammoth Heights ElementaryExterior Wall ConstructionRecaulk expansion joints. Reseal CMU.2 \$Mammoth Heights ElementaryAsphalt PlaygroundResurface asphalt playground.2 \$Mammoth Heights ElementaryPaving & SurfacingResurface asphalt parking lot.2 \$Mammoth Heights ElementaryIntercommunication & Paging SystemInstall new IP intercom system for building.1 \$Mammoth Heights ElementaryFire Alarm SystemsUpgrade fire alarm system.1 \$Mammoth Heights ElementaryControlsUpgrade control system.1 \$Meadow View ElementaryAsphalt PlaygroundReplace playground asphalt play pad.2 \$Meadow View ElementaryChilled Water SystemsReplace cooling tower.1 \$Meadow View ElementaryPaving & SurfacingResurface asphalt parking lot.2 \$	961,586 31,812 134,740 250,025 288,542 403,958
Mammoth Heights ElementaryExterior Wall ConstructionRecaulk expansion joints. Reseal CMU.2 \$Mammoth Heights ElementaryAsphalt PlaygroundResurface asphalt playground.2 \$Mammoth Heights ElementaryPaving & SurfacingResurface asphalt parking lot.2 \$Mammoth Heights ElementaryIntercommunication & Paging SystemInstall new IP intercom system for building.1 \$Mammoth Heights ElementaryFire Alarm SystemsUpgrade fire alarm system.1 \$Mammoth Heights ElementaryControlsUpgrade control system.1 \$Meadow View ElementaryAsphalt PlaygroundReplace playground asphalt play pad.2 \$Meadow View ElementaryChilled Water SystemsReplace cooling tower.1 \$Meadow View ElementaryPaving & SurfacingResurface asphalt parking lot.2 \$	31,812 134,740 250,025 288,542 403,958
Mammoth Heights Elementary Asphalt Playground Resurface asphalt playground. 2 \$ Mammoth Heights Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$ Mammoth Heights Elementary Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Mammoth Heights Elementary Fire Alarm Systems Upgrade fire alarm system. 1 \$ Mammoth Heights Elementary Controls Upgrade control system. 1 \$ Meadow View Elementary Asphalt Playground Replace playground asphalt play pad. 2 \$ Meadow View Elementary Chilled Water Systems Replace cooling tower. 1 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$	134,740 250,025 288,542 403,958
Mammoth Heights Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$ Mammoth Heights Elementary Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Mammoth Heights Elementary Fire Alarm Systems Upgrade fire alarm system. 1 \$ Mammoth Heights Elementary Controls Upgrade for ealarm system. 1 \$ Meadow View Elementary Asphalt Playground Replace playground asphalt play pad. 2 \$ Meadow View Elementary Chilled Water Systems Replace cooling tower. 1 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$	250,025 288,542 403,958
Mammoth Heights Elementary Intercommunication & Paging System Install new IP intercom system for building. 1 \$ Mammoth Heights Elementary Fire Alarm Systems Upgrade fire alarm system. 1 \$ Mammoth Heights Elementary Controls Upgrade control system. 1 \$ Meadow View Elementary Asphalt Playground Replace playground asphalt play pad. 2 \$ Meadow View Elementary Chilled Water Systems Replace cooling tower. 1 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$	288,542 403,958
Mammoth Heights ElementaryFire Alarm SystemsUpgrade fire alarm system.1 \$Mammoth Heights ElementaryControlsUpgrade control system.1 \$Meadow View ElementaryAsphalt PlaygroundReplace playground asphalt play pad.2 \$Meadow View ElementaryChilled Water SystemsReplace cooling tower.1 \$Meadow View ElementaryPaving & SurfacingResurface asphalt parking lot.2 \$	403,958
Mammoth Heights Elementary Controls Upgrade control system. 1 \$ Meadow View Elementary Asphalt Playground Replace playground asphalt play pad. 2 \$ Meadow View Elementary Chilled Water Systems Replace cooling tower. 1 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$	
Meadow View Elementary Asphalt Playground Replace playground asphalt play pad. 2 \$ Meadow View Elementary Chilled Water Systems Replace cooling tower. 1 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$	740,481
Meadow View Elementary Asphalt Playground Replace playground asphalt play pad. 2 \$ Meadow View Elementary Chilled Water Systems Replace cooling tower. 1 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$	
Meadow View Elementary Chilled Water Systems Replace cooling tower. 1 \$ Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$	134,740
Meadow View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$	240,429
, 0 0	250,025
Meadow View Elementary Intercommunication & Paging System Install new IP intercom system for building.	288,542
Mesa Middle School Exterior Wall Construction Recaulk expansion joints. Reseal CMU.	52,976
Mesa Middle School Sink Countertops Replace sink counter tops.	81,107
Mesa Middle School Emergency Light & Power Systems Replace generator and associated equipment. Re-support gas piping.	144,337
Mesa Middle School Intercommunication & Paging System Install new IP intercom system for building.	384,635
Mesa Middle School Fire Alarm Systems Upgrade fire alarm system. 1 \$	653,984
Mesa Middle School Controls Upgrade control system. 1 \$	1,250,128
Mountain Ridge Middle School Emergency Light & Power Systems Replace generator and associated equipment.	144,337
Mountain Ridge Middle School Intercommunication & Paging System Install new IP intercom system for building.	384,635
Mountain Ridge Middle School Carpeting Replace carpet. 2 \$	1,375,141
Mountain Ridge Middle School Roof Finishes Replace .060 EPDM ballasted with .060 fully adhered. 1 \$	1,923,172
Mountain View Elementary Wash Fountains Replace trough washing stations with sinks (6). 2 \$	33,915
Mountain View Elementary Asphalt Playground Resurface asphalt playground. 2 \$	134,740
Mountain View Elementary Intercommunication & Paging System Install new IP intercom system for building. 1 \$	288,542
Mountain View Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$	384,635
Mountain View Lichterhary Faving & Surfacing Replace VCT. 2 \$	144,337
	144,337
Mountain Vista High School Flooring Replace VCT in pod hallways, classrooms as needed.	158,665
Mountain Vista High School Theater & Stage Equipment Upgrade lighting and sound systems. 2 \$	192,317
Mountain Vista High School Carpeting Replace carpet in classrooms and offices. 2 \$	384,635
Mountain Vista High School Intercommunication & Paging System Install new IP intercom system for building.	480,859
Mountain Vista High School Direct Expansion Systems Replace RTUs. 1 \$	4,807,930
Northeast Elementary Asphalt Playground Resurface playground play pads. 2 \$	134,740
Northeast Elementary Flooring Replace poured acrylic floor in kitchen. 2 \$	144,337
Northeast Elementary Intercommunication & Paging System Install new IP intercom system for building.	288,542
Northeast Elementary Paving & Surfacing Resurface asphalt parking lot. 2 \$	384,635
Northridge Elementary Flooring Replace ceramic tile floor with MMA. 2 \$	144,337
Northridge Elementary Intercommunication & Paging System Install new IP intercom system for building.	288,542
Northridge Elementary Fire Alarm Systems Upgrade fire alarm system. 1 \$	336,654
Pine Grove Elementary Sink Countertops Replace sink countertops with single surface. 2 \$	57,708
Pine Grove Elementary Switchgear Replace main switchgear. 1 \$	192,317
Pine Grove Elementary	192,317
	250,025
	288,542
Pine Grove Elementary Intercommunication & Paging System Install new IP intercom system for building.	
Pine Grove Elementary Fire Alarm Systems Upgrade fire alarm system.	336,654
Pine Grove Elementary Controls Upgrade control system. 1 \$	576,951
Pine Lane Elementary Flooring Replace VCT (north building). 2 \$	63,493
Pine Lane Elementary Flooring Replace VCT with poured acrylic. Abatement (north building). 2 \$	177,068
Pine Lane Elementary Intercommunication & Paging System Install new IP intercom system for north building.	288,542
Pine Lane Elementary Wash Fountains Replace south building trough washing stations with sinks (6).	33,915
Pine Lane Elementary Flooring Replace VCT in kitchen with poured acrylic (south building). 2 \$	144,337
Pine Lane Elementary Intercommunication & Paging System Install new IP intercom system for south building.	288,542
Pine Lane Elementary Direct Expansion Systems Replace RTUs (south building). 1 \$	1,923,172
Pioneer Elementary Flooring Replace VCT in art room. 2 \$	15,906
Pioneer Elementary Flooring Replace VCT. 2 \$	38,516
Pioneer Elementary Sink Countertops Replace sink countertops with single surface. 2 \$	57,708
Pioneer Elementary	134,740
	250,025
Pioneer Elementary Intercommunication & Paging System Install new IP intercom system for building.	288,542
Pioneer Elementary Boilers Replace boiler(s). 1 \$	480,859
Plum Creek Academy Intercommunication & Paging System Install new IP intercom system for building.	144,337
Plum Creek Academy Fire Alarm Systems Upgrade fire alarm system. 1 \$	230,834
Plum Creek Academy Controls Upgrade control system. 1 \$	288,542
Ponderosa High School Exterior Wall Construction Recaulk control joints. 2 \$	18,929

	hw	In the second second		•	44.400
Ponderosa High School	Wash Fountains	Poor condition, need replaced.	2	\$	44,432 144,337
Ponderosa High School Ponderosa High School	Emergency Light & Power Systems Theater & Stage Equipment	Replace generator and associated equipment. Upgrade lighting and sound systems.	2	\$	192,317
Ponderosa High School	Chilled Water Systems	Replace cooling tower.	1	\$	240,429
Ponderosa High School	Intercommunication & Paging System	Install new IP intercom system for building.	1	\$	480,859
Ponderosa High School	Paving & Surfacing	Resurface asphalt parking lot.	2	\$	2,884,758
Prairie Crossing Elementary	Flooring	Replace sheet vinyl flooring with MMA.	2	\$	77,032
Prairie Crossing Elementary	Asphalt Playground	Replace asphalt playground.	2	\$	134,740
Prairie Crossing Elementary	Chilled Water Systems	Replace cooling tower.	1	\$	240,429
Prairie Crossing Elementary	Paving & Surfacing	Resurface asphalt parking lot.	2	\$	250,025
Prairie Crossing Elementary		Install new IP intercom system for building.	1	\$	288,542
Ranch View Middle School	Sink Countertops	Replace sink counter tops in all restrooms.	2	\$	81,107
Ranch View Middle School	Flooring	Replace VCT.	2	\$	96,224
Ranch View Middle School	Flooring	Replace original sheet vinyl flooring with poured acrylic in all	2	\$	96,224
Ranch View Middle School	Emergency Light & Power Systems	Replace generator and associated equipment.	1	\$	144,337
Ranch View Middle School	Hot Water Service	Replace domestic hot water system, heaters, pumps, and storage.	1	\$	165,107
Ranch View Middle School	Passenger Elevators	Overhaul elevator.	1	\$	288,542
Ranch View Middle School		Install new IP intercom system for building.	1	\$	384,635
Ranch View Middle School	Boilers	Replace boiler(s).	1	\$	576,951
Ranch View Middle School	Chilled Water Systems	Replace chiller.	1	\$	576,951
Redstone Elementary	Exterior Wall Construction	Recaulk control joints.	2	\$	7,625
Redstone Elementary	Exterior Wall Construction	CMU needs sealed. Repair cracks at joints left of main entrance and	2	\$	29,445
Redstone Elementary Redstone Elementary	Sink Countertops	Replace sink countertops with single surface. Replace VCT.	2	\$	42,854
Redstone Elementary Redstone Elementary	Flooring Flooring	Replace VC1. Replace gym carpet.	2	_	48,113 77,032
Redstone Elementary	Flooring	Replace gym carpet. Replace poured acrylic flooring in all restrooms.	2	\$	77,032
Redstone Elementary	Emergency Light & Power Systems	Replace generator and associated equipment.	1	\$	144,337
Redstone Elementary	Intercommunication & Paging System		1	\$	288.542
Redstone Elementary	Carpeting	Replace carpet.	2	\$	673,176
Renaissance Magnet School	Exterior Wall Construction	Repair cracks in walls.	2	\$	5,521
Renaissance Magnet School	Sink Countertops	Resurface restroom countertops.	2	\$	13,803
Renaissance Magnet School		Install new IP intercom system for building.	1	\$	288,542
Rock Canyon High School	Sink Countertops	Replace sink counter tops in all restrooms.	2	\$	81,107
Rock Canyon High School	Exterior Wall Construction	Reseal CMU, recaulk control joints.	2	\$	119,360
Rock Canyon High School	Emergency Light & Power Systems	Replace generator and associated equipment.	1	\$	144,337
Rock Canyon High School	Flooring	Replace VCT.	2	\$	144,337
Rock Canyon High School	Flooring	Replace poured acrylic flooring in all restrooms.	2	\$	144,337
Rock Canyon High School	Theater & Stage Equipment	Upgrade lighting and sound systems.	2	\$	192,317
Rock Canyon High School		Install new IP intercom system for building.	1	\$	480,859
Rock Canyon High School	Carpeting	Replace carpet.	2	\$	1,442,445
Rock Canyon High School	Direct Expansion Systems	Replace RTUs.	1	\$	4,807,930
Rock Ridge Elementary Rock Ridge Elementary	Flooring Flooring	Replace gym carpet.	2	\$	77,032 144,337
Rock Ridge Elementary	ŭ	Replace kitchen flooring. Install new IP intercom system for building.	2 1	\$	288,542
Rock Ridge Elementary	Carpeting	Replace carpet.	2		673,176
Rocky Heights Middle School	Exterior Wall Construction	Recaulk building control joints.	2	\$	19,324
Rocky Heights Middle School	Flooring	Replace sheet vinyl with poured acrylic, some rest rooms complete.	2	\$	19,324
Rocky Heights Middle School	Sink Countertops	Replace sink countertops in all restrooms with single surface.	2	\$	77.032
Rocky Heights Middle School	Flooring	Replace VCT.	2	\$	96,224
Rocky Heights Middle School	Emergency Light & Power Systems	Replace generator and associated equipment.	1	\$	144,337
Rocky Heights Middle School		Install new IP intercom system for building.	1	\$	384,635
Rocky Heights Middle School	Carpeting	Replace carpet.	2	\$	1,375,141
Rocky Heights Middle School		Replace .060 EPDM ballasted with .060 fully adhered.		\$	1,923,172
Roxborough Intermediate	Exterior Wall Construction	Recaulk expansion joints. Reseal CMU.	2	\$	31,812
Roxborough Intermediate	Intercommunication & Paging System	Install new IP intercom system for building.		\$	288,542
Roxborough Intermediate	Fire Alarm Systems	Upgrade fire alarm system.		\$	403,958
Roxborough Intermediate	Controls	Upgrade control system.	1	\$	740,481
Roxborough Primary	Emergency Light & Power Systems	Replace generator and associated equipment.	1	\$	144,337
Roxborough Primary	Flooring	Replace kitchen flooring with poured acrylic.		\$	144,337
Roxborough Primary	Switchgear	Replace main switchgear.		\$	211,641
Roxborough Primary	Panels & Transformers	Replace original panels and transformers.	1	\$	211,641 288,542
Roxborough Primary	Intercommunication & Paging System Fire Alarm Systems		<u>1</u>	\$	307,734
Roxborough Primary Roxborough Primary	Controls	Upgrade fire alarm system. Upgrade control system.	1	_	576,951
Roxborough Primary	Carpeting	Replace carpet.		\$	673,176
Saddle Ranch Elementary	Sink Countertops	Replace sink countertops with single surface.		\$	57,708
Saddle Ranch Elementary	Flooring	Replace epoxy floor with MMA.	2	\$	144,337
Saddle Ranch Elementary		Install new IP intercom system for building.	1	\$	288,542
Sage Canyon Elementary	Intercommunication & Paging System		1	_	288,542
Sage Canyon Elementary	Fire Alarm Systems	Upgrade fire alarm system.		\$	403,958
Sage Canyon Elementary	Controls	Upgrade control system.	1	\$	673,176
Sagewood Middle School	Sink Countertops	Replace sink countertops with single surface.	2		57,708
Sagewood Middle School	Passenger Elevators	Overhaul elevator.	1	\$	288,542
Sagewood Middle School	Intercommunication & Paging System		1		384,635
Sagewood Middle School	Paving & Surfacing	Resurface asphalt parking lot.	2	\$	384,635
Sagewood Middle School	Boilers	Replace boiler(s).	1		576,951
Sand Creek Elementary	Hot Water Service	Replace domestic water heater and associated piping.	1	\$	178,383
Sand Creek Elementary		Install new IP intercom system for building.	1	\$	288,542
Sand Creek Elementary	Carpeting	Replace carpet.	2		634,660
Sedalia Elementary	Flooring	Replace red ceramic tile in hallway, showing wear and cracks.		\$	22,084
Sedalia Elementary	Terminal Self-Contained Units	Replace unit heaters at entries.	1	\$	84,656

Sedalia Elementary	Intercommunication & Dening Custom	Install new IP intercom system for building.		\$	288,542
Sierra Middle School	Sink Countertops	Replace sink countertops as necessary.	2		56,788
Sierra Middle School		Replace poured acrylic flooring in all restrooms.	2		96,224
Sierra Middle School		Install new IP intercom system for building.		\$	384,635
Soaring Hawk Elementary	Exterior Wall Construction	CMU needs sealed.	2		24,582
Soaring Hawk Elementary	Flooring	Replace gym carpet.	2		77,032
Soaring Hawk Elementary	Flooring	Replace poured acrylic flooring in all restrooms.	2		77,032
Soaring Hawk Elementary	Emergency Light & Power Systems	Replace generator and associated equipment.	1	\$	144,337
Soaring Hawk Elementary		Install new IP intercom system for building.		\$	288,542
Soaring Hawk Elementary	Carpeting	Replace carpet.	2		673,176
South Ridge Elementary	Switchgear	Replace main switchgear.		\$	192,317
South Ridge Elementary	Panels & Transformers	Replace panels and transformers not yet replaced.	1		192,317
South Ridge Elementary		Install new IP intercom system for building.		\$	288,542
South Ridge Elementary	Fire Alarm Systems	Upgrade fire alarm system.	1		288,542
Stone Mountain Elementary	Exterior Wall Construction	Recaulk expansion joints. Reseal CMU.	2		31,812
Stone Mountain Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	1	\$	288,542
Stone Mountain Elementary	Fire Alarm Systems	Upgrade fire alarm system.	1	\$	403,958
Stone Mountain Elementary	Controls	Upgrade control system.	1	\$	740,481
Summit View Elementary	Flooring	Replace VCT flooring in staff restrooms.	2	\$	3,681
Summit View Elementary	Switchgear	Replace main switchgear.	1	\$	63,493
Summit View Elementary	Panels & Transformers	Replace original panels and transformers.	1	\$	211,641
Summit View Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	1	\$	288,542
Summit View Elementary	Fire Alarm Systems	Upgrade fire alarm system.	1	\$	375,038
Summit View Elementary	Controls	Upgrade control system.	1	\$	576,951
Summit View Elementary	Carpeting	Replace carpet.	2		673,176
Teddy Lane	Direct Expansion Systems	Replace RTU.	1	\$	480,859
ThunderRidge High School	Theater & Stage Equipment	Replace small stage curtains and cracked seats in auditorium.	2	\$	35,755
ThunderRidge High School	Exterior Wall Construction	Recaulk control joints. Re-seal CMU.	2	\$	112,393
ThunderRidge High School	Theater & Stage Equipment	Upgrade lighting and sound systems.	2	\$	192,317
ThunderRidge High School	Intercommunication & Paging System	Install new IP intercom system for building.	1	\$	288,542
ThunderRidge High School	Boilers	Replace boiler(s).	1	_	769,269
ThunderRidge High School	Paving & Surfacing	Resurface asphalt parking lot.	2	\$	2,884,758
Timber Trail Elementary	Flooring	Replace VCT.	2		38,516
Timber Trail Elementary	Sink Countertops	Replace sink countertops with single surface.	2		57,708
Timber Trail Elementary	Flooring	Replace gym carpet with sport flooring.	2		77,032
Timber Trail Elementary	Flooring	Replace poured acrylic flooring in all restrooms.	2		77,032
Timber Trail Elementary	Emergency Light & Power Systems	Replace generator and associated equipment.	1	_	144,337
Timber Trail Elementary	Paving & Surfacing	Resurface asphalt parking lot.	2		153,933
Timber Trail Elementary		Install new IP intercom system for building.	1	\$	288,542
Timber Trail Elementary	Carpeting	Replace carpet.	2		634,660
Trailblazer Elementary	Flooring	Replace VCT.	2		38,516
Trailblazer Elementary	Flooring	Replace kitchen flooring with poured acrylic. Currently Hubelite	2	_	144,337
Trailblazer Elementary		Install new IP intercom system for building.		\$	288,542
Wildcat Mountain Elementary	Flooring	Replace VCT in classrooms due to building movement.	2		19,718
Wildcat Mountain Elementary	Flooring	Replace VCT in classrooms due to building movement.	2		38,516
Wildcat Mountain Elementary Wildcat Mountain Elementary	Flooring	Flooring Kitchen. Needs-Replace kitchen flooring.	2		144.337
Wildcat Mountain Elementary Wildcat Mountain Elementary		Install new IP intercom system for building.		_	288,542
Wildcat Mountain Elementary Wildcat Mountain Elementary					
	Boilers	Replace boiler(s).	1		480,859
Wildcat Mountain Elementary	Chilled Water Systems	Replace chiller.	1	\$	576,951
	1				

CAPITAL RENEWAL & REPLACEMENT: DISTRICT EDUCATIONAL FACILITIES TOTAL \$ 126,268,173