Capital Renewal & Replacement: Detailed District School Planned Project List*

*Project scope and list may vary slightly based on actual cost at the time the work is performed and emerging system needs and priorities. DRAFT Bond Plan August 9, 2022

School	Category	Description	Esti	mated Cost
Acres Green Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	\$	264,717
Acres Green Elementary	Boilers	Replace boiler(s).	\$	441,155
Acres Green Elementary	Direct Expansion Systems	Replace RTUs originally installed in 2000.	\$	1,764,378
Arrowwood Elementary	Flooring	Replace original epoxy floor.	\$	70,672
Arrowwood Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	\$	264,717
Arrowwood Elementary	Boilers	Replace boiler(s).	\$	441,155
Arrowwood Elementary	Chilled Water Systems	Replace chiller.	\$	529,313
Bear Canyon Elementary	Flooring	Replace VCT flooring in staff restrooms.	\$	7,115
Bear Canyon Elementary	Carpeting	Replace carpet in workrooms in stacked pods.	\$	88,279
Bear Canyon Elementary	Switchgear	Replace main switchgear.	\$	176,438
Bear Canyon Elementary	Panels & Transformers	Replace original panels and transformers.	\$	194,166
Bear Canyon Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	\$	264,717
Bear Canyon Elementary	Fire Alarm Systems	Upgrade fire alarm system.	\$	282,325
Bear Canyon Elementary	Controls	Upgrade control system.	\$	529,313
Buffalo Ridge Elementary	Exterior Wall Construction	Recaulk control joints.	\$	6,271
Buffalo Ridge Elementary	Asphalt Playground	Playpad needs resurfacing.	\$	123,615
Buffalo Ridge Elementary	Paving & Surfacing	Resurface asphalt parking lot.	\$	229,381
Buffalo Ridge Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	\$	264,717
Buffalo Ridge Elementary	Boilers	Replace boiler(s).	\$	441,155
Castle Rock Elementary	Flooring	Replace VCT.	\$	44,140
Castle Rock Elementary	Flooring	Replace gym carpet.	\$	70,672
Castle Rock Elementary	Flooring	Replace original ceramic tile with poured acrylic.	\$	70,672
Castle Rock Elementary	Emergency Light & Power Systems	Replace generator and associated equipment.	\$	132,419
Castle Rock Elementary	Flooring	Replace ceramic tile floor with MMA.	\$	132,419
Castle Rock Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	\$	264,717
Castle Rock Middle School	Exterior Wall Construction	Recaulk control joints.	\$	8,563
Castle Rock Middle School	Theater & Stage Equipment	Upgrade Strand controller.	\$	8,563
Castle Rock Middle School	Flooring	Replace kitchen flooring. Currently red hubblelite.	\$	132,419
Castle Rock Middle School	Intercommunication & Paging System	Install new IP intercom system for building.	\$	352,876
Castle Rock Middle School	Boilers	Replace boiler(s).	\$	441,155
Castle View High School	Exterior Wall Construction	Re-seal CMU, recaulk control joints.	\$	111,073
Castle View High School	Theater & Stage Equipment	Upgrade lighting and sound systems.	\$	176,438
Castle View High School	Intercommunication & Paging System	Install new IP intercom system for building.	\$	441,155
Chaparral High School	Theater & Stage Equipment	Replace cracked seats in auditorium.	\$	5,548
Chaparral High School	Sink Countertops	Replace sink counter tops in all restrooms.	\$	74,410
Chaparral High School	Exterior Wall Construction	Recaulk control joints. Re-seal CMU.	\$	103,113
Chaparral High School	Flooring	Replace original hubblelite floor with MMA.	\$	132,419
Chaparral High School	Theater & Stage Equipment	Upgrade lighting and sound systems.	\$	176,438
Chaparral High School		Install new IP intercom system for building.	\$	264,717
Chaparral High School	Boilers	Replace boiler(s).	\$	705,751
Cherokee Trail Elementary	Flooring	Replace kitchen flooring.	\$	132,419

Cherokee Trail Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	\$ 264,717
Cherokee Trail Elementary	Controls	Upgrade control system.	\$ 529,313
Cherokee Trail Elementary	Carpeting	Replace carpet.	\$ 617,593
Cherry Valley Elementary	Flooring	Replace kitchen flooring.	\$ 35,336
Cherry Valley Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	\$ 88,279
Cherry Valley Elementary	Carpeting	Replace carpet in all buildings, includes modular classrooms.	\$ 161,483
Cimarron Middle School	Intercommunication & Paging System	Install new IP intercom system for building.	\$ 352,876
Cimarron Middle School	Controls	Upgrade control system.	\$ 617,593
Cimarron Middle School	Fire Alarm Systems	Upgrade fire alarm system.	\$ 661,732
Clear Sky Elementary	Exterior Wall Construction	Recaulk expansion joints. Reseal CMU.	\$ 29,185
Clear Sky Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	\$ 264,717
Clear Sky Elementary	Fire Alarm Systems	Upgrade fire alarm system.	\$ 370,604
Clear Sky Elementary	Controls	Upgrade control system.	\$ 679,340
Copper Mesa Elementary	Flooring	Replace VCT.	\$ 44,140
Copper Mesa Elementary	Flooring	Replace gym carpet.	\$ 70,672
Copper Mesa Elementary	Flooring	Replace poured acrylic flooring in all restrooms.	\$ 70,672
Copper Mesa Elementary		Replace generator and associated equipment.	\$ 132,419
Copper Mesa Elementary		Install new IP intercom system for building.	\$ 264,717
Copper Mesa Elementary	Carpeting	Replace carpet.	\$ 617,593
Cougar Run Elementary	Flooring	Replace VCT in classrooms.	\$ 19,296
Cougar Run Elementary	Flooring	Replace sheet vinyl flooring in art room.	\$ 22,552
Cougar Run Elementary	Flooring	Replace VCT.	\$ 35,336
Cougar Run Elementary	Sink Countertops	Replace sink countertops with single surface.	\$ 52,943
Cougar Run Elementary	Flooring	Replace red hubblelite floor with poured acrylic.	\$ 132,419
Cougar Run Elementary	Theater & Stage Equipment	Upgrade gym sound system.	\$ 155,333
Cougar Run Elementary		Install new IP intercom system for building.	\$ 264,717
Cougar Run Elementary	Boilers	Replace boiler(s).	\$ 441,155
Coyote Creek Elementary	Flooring	Replace poured acrylic flooring in all restrooms.	\$ 70,672
Coyote Creek Elementary	Flooring	Replace flooring.	\$ 132,419
Coyote Creek Elementary	Switchgear	Replace main switchgear.	\$ 176,438
Coyote Creek Elementary		Replace original panels and transformers.	\$ 176,438
Coyote Creek Elementary		Install new IP intercom system for building.	\$ 264,717
Coyote Creek Elementary	Fire Alarm Systems	Upgrade fire alarm system.	\$ 282,325
Coyote Creek Elementary	Controls	Upgrade control system.	\$ 529,313
Coyote Creek Elementary	Carpeting	Replace carpet.	\$ 617,593
Cresthill Middle School	Flooring	Replace kitchen flooring, original poured acrylic.	\$ 132,419
Cresthill Middle School	Panels & Transformers	Replace original panels and transformers.	\$ 194,166
Cresthill Middle School		Install new IP intercom system for building.	\$ 352.876
Cresthill Middle School	Fire Alarm Systems	Upgrade fire alarm system.	\$ 617,593
Cresthill Middle School	Controls	Upgrade control system.	\$ 1,058,627
Cresthill Middle School	Carpeting	Replace carpet.	\$ 1,323,344
DC Oakes High School		Replace condensing units.	\$ 132.419
DC Oakes High School		Install new IP intercom system for building.	\$ 132,419
DC Oakes High School		Replace generator and associated equipment.	\$ 132,419
DC Oakes High School	Carpeting	Replace generator and associated equipment.	\$ 264,717
ŭ			 · · ·
Douglas County High School	Theater & Stage Equipment	South 100A Stage/Dance, replace damaged curtain and track system.	\$ 32,803

Douglas County High School	Flooring	Replace ceramic tile flooring with seamless acrylic in two sets of restrooms at 2 story addition.	\$	35,336
Douglas County High School	Emergency Light & Power Systems	Replace generator and associated equipment.	\$	132.419
Douglas County High School	Theater & Stage Equipment	Auditorium theatrical equipment old and not comparable with other high schools.	\$	155,333
Douglas County High School	Theater & Stage Equipment	Upgrade lighting and sound systems.	\$	176,438
Douglas County High School		Install new IP intercom system for building.	\$	352,876
Douglas County High School	Flooring	South 104B Office, 50, 50B, 53B, 66A remove and replace VCT beyond life.	\$	14,593
Douglas County High School	Flooring	Replace poured acrylic flooring in all south building restrooms.	\$	88,279
Douglas County High School		Install new IP intercom system for south building.	\$	352,876
Eagle Ridge Elementary	Flooring	Replace epoxy floor with MMA.	\$	132,419
Eagle Ridge Elementary		Install new IP intercom system for building.	\$	264,717
Early Childhood Center-CR		Install new IP intercom system for building.	\$	132,419
Early Childhood Center-CR	Fire Alarm Systems	Upgrade fire alarm system.	\$	211,774
Eldorado Elementary	Flooring	Replace VCT in classrooms.	\$	14,593
Eldorado Elementary	Sink Countertops	Replace sink countertops with single surface.	\$	52,943
Eldorado Elementary	Flooring	Replace sheet vinyl flooring with MMA.	\$	70,672
Eldorado Elementary	Flooring	Replace kitchen floor.	\$	132,419
Eldorado Elementary	Chilled Water Systems	Replace cooling tower.	\$	220,577
Eldorado Elementary		Install new IP intercom system for building.	\$	264.717
Flagstone Elementary	Exterior Wall Construction	Recaulk building control joints. Seal CMU.	\$	29,185
Flagstone Elementary	Emergency Light & Power Systems	Replace generator and associated equipment.	\$	132,419
Flagstone Elementary	Chilled Water Systems	Replace cooling tower.	\$	220,577
Flagstone Elementary		Install new IP intercom system for building.	\$	264.717
Flagstone Elementary	Chilled Water Systems	Upgrade chiller.	\$	529,313
Flagstone Elementary	Carpeting	Replace carpet.	\$	617,593
Fox Creek Elementary	Flooring	Replace VCT in classrooms.	\$	52,702
Fox Creek Elementary	Flooring	Replace kitchen flooring with MMA.	\$	132,419
Fox Creek Elementary	Switchgear	Replace main switchgear.	\$	176.438
		Replace original panels and transformers.		-,
Fox Creek Elementary Fox Creek Elementary	Panels & Transformers	Install new IP intercom system for building.	\$	176,438 264,717
Fox Creek Elementary		Upgrade fire alarm system.	ه \$	282,325
Fox Creek Elementary	Fire Alarm Systems			282,325
	Controls	Upgrade control system.	\$	
Franktown Elementary	Wash Fountains	Replace trough washing stations with sinks (6).	\$	31,115
Franktown Elementary		Install new IP intercom system for building.	\$	264,717 52,943
Frontier Valley Elementary	Sink Countertops	Replace sink countertops with single surface.	\$	
Frontier Valley Elementary	Flooring	Replace sheet vinyl flooring with MMA.	\$	70,672
Frontier Valley Elementary	Chilled Water Systems	Replace cooling tower.	\$	220,577
Frontier Valley Elementary		Install new IP intercom system for building.	\$	264,717
Gold Rush Elementary	Exterior Wall Construction	Repair flashing on east side front entry.	\$	3,015
Gold Rush Elementary	Exterior Wall Construction	Recaulk expansion joints. Reseal CMU.	\$	29,185
Gold Rush Elementary		Install new IP intercom system for building.	\$	264,717
Gold Rush Elementary	Fire Alarm Systems	Upgrade fire alarm system.	\$	370,604
Gold Rush Elementary	Controls	Upgrade control system.	\$	679,340
Heritage Elementary	Flooring	Replace VCT.	\$	40,160
Heritage Elementary	Flooring	Replace poured acrylic kitchen flooring.	\$	120,359
Heritage Elementary		Install new IP intercom system for building.	\$	264,717
Highlands Ranch High School	Flooring	Replace sheet vinyl with MMA 4 student restrooms, coat tile restrooms with MMA.	\$	70,672

Highlands Ranch High School	Theater & Stage Equipment	Replace auditorium seating.	\$	116,500
Highlands Ranch High School		Replace kitchen flooring.	\$	132,419
Highlands Ranch High School		Upgrade lighting and sound systems.	\$	176,438
		Install new IP intercom system for building.	\$	441,155
Highlands Ranch High School		Replace VCT.	\$	2,096,149
Highlands Ranch High School		Resurface asphalt parking lot.	\$	2,646,567
		Replace main hallway restrooms with poured acrylic. Pod restrooms complete.	\$	15,557
	Hot Water Distribution	DHW heater needs replaced.	\$	33,286
Iron Horse Elementary		Replace sink countertops with single surface.	\$	52,943
		Install new IP intercom system for building.	\$	264,717
Iron Horse Elementary	Boilers	Replace boiler(s).	\$	441,155
			\$	10,492
		Replace trough washing stations with sinks (2).	\$	70,672
Larkspur Elementary		Replace ceramic tile with MMA.		
Larkspur Elementary	Switchgear	Replace main switchgear.	\$	176,438
		Replace panels and transformers not yet replaced.	\$	176,438
Larkspur Elementary		Replace boiler(s).	\$	264,717
		Install new IP intercom system for building.	\$	264,717
		Resurface asphalt parking lot.	\$	1,764,378
	Roof Finishes	Replace roof.	\$	2,646,567
	Flooring	Replace VCT.	\$	35,336
Legacy Point Elementary		Replace gym carpet with sport flooring.	\$	70,672
		Replace generator and associated equipment.	\$	132,419
		Replace generator and associated equipment.	\$	132,419
		Replace cooling tower.	\$	220,577
	Intercommunication & Paging System	Install new IP intercom system for building.	\$	264,717
Legacy Point Elementary	Flooring	Replace carpet.	\$	617,593
Legend High School	Exterior Wall Construction	Repair moisture penetration at F pod entrance.	\$	9,769
Legend High School	Theater & Stage Equipment	Upgrade lighting and sound systems.	\$	176,438
Legend High School		Install new IP intercom system for building.	\$	441,155
		Upgrade fire alarm system.	\$	617,593
Legend High School		Upgrade control system.	\$	1,843,853
Lone Tree Elementary	Flooring	Repair VCT at cafeteria entrance.	\$	3,980
Lone Tree Elementary	Exterior Wall Construction	Recaulk control joints. Seal masonry CMU.	\$	29,185
Lone Tree Elementary		Replace sink counter tops in all restrooms.	\$	52,943
		Upgrade fire alarm system.	\$	247,109
Lone Tree Elementary		Install new IP intercom system for building.	\$	264,717
Lone Tree Elementary		Upgrade control system.	\$	582,257
		Replace .045 EDPM ballasted roof with .060 EDPM fully adhered.	\$	882,189
Mammoth Heights Elementary		Recaulk expansion joints. Reseal CMU.	\$	29,185
Mammoth Heights Elementary		Resurface asphalt playground.	\$	123,615
Mammoth Heights Elementary		Resurface asphalt parking lot.	\$	229,381
		Install new IP intercom system for building.	\$	264,717
Mammoth Heights Elementary		Upgrade fire alarm system.	\$	370.604
Mammoth Heights Elementary		Upgrade control system.	\$	679,340
		Replace playground asphalt play pad.	\$	123,615
		Replace playground asphan play pad. Replace cooling tower.	\$	220,577
		Resurface asphalt parking lot.		220,577 229,381
INICAUUW VIEW CIEITIEITIAI Y	r aving a Sunacing	n countable appliant parking lon.	φ	229,301

Meadow View Elementary		Install new IP intercom system for building.	\$ 264,717
Mesa Middle School	Exterior Wall Construction	Recaulk expansion joints. Reseal CMU.	\$ 48,602
Mesa Middle School	Sink Countertops	Replace sink counter tops.	\$ 74,410
		Replace generator and associated equipment. Re-support gas piping.	\$ 132,419
Mesa Middle School		Install new IP intercom system for building.	\$ 352,876
Mesa Middle School	Fire Alarm Systems	Upgrade fire alarm system.	\$ 599,985
Mesa Middle School	Controls	Upgrade control system.	\$ 1,146,906
		Replace generator and associated equipment.	\$ 132,419
		Install new IP intercom system for building.	\$ 352,876
Mountain Ridge Middle School		Replace carpet.	\$ 1,261,597
Mountain Ridge Middle School	Roof Finishes	Replace .060 EPDM ballasted with .060 fully adhered.	\$ 1,764,378
,	Wash Fountains	Replace trough washing stations with sinks (6).	\$ 31,115
Mountain View Elementary	Asphalt Playground	Resurface asphalt playground.	\$ 123,615
		Install new IP intercom system for building.	\$ 264,717
	Paving & Surfacing	Resurface asphalt parking lot.	\$ 352,876
	Flooring	Replace VCT.	\$ 132,419
Mountain Vista High School	Flooring	Replace flooring in all restrooms.	\$ 132,419
Mountain Vista High School	Flooring	Replace VCT in pod hallways, classrooms as needed.	\$ 145,564
Mountain Vista High School	Theater & Stage Equipment	Upgrade lighting and sound systems.	\$ 176,438
	Carpeting	Replace carpet in classrooms and offices.	\$ 352,876
Mountain Vista High School	Intercommunication & Paging System	Install new IP intercom system for building.	\$ 441,155
Mountain Vista High School	Direct Expansion Systems	Replace RTUs.	\$ 4,410,945
Northeast Elementary	Asphalt Playground	Resurface playground play pads.	\$ 123,615
Northeast Elementary	Flooring	Replace poured acrylic floor in kitchen.	\$ 132,419
Northeast Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	\$ 264,717
Northeast Elementary	Paving & Surfacing	Resurface asphalt parking lot.	\$ 352,876
Northridge Elementary	Flooring	Replace ceramic tile floor with MMA.	\$ 132,419
Northridge Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	\$ 264,717
Northridge Elementary	Fire Alarm Systems	Upgrade fire alarm system.	\$ 308,857
Pine Grove Elementary	Sink Countertops	Replace sink countertops with single surface.	\$ 52,943
Pine Grove Elementary	Switchgear	Replace main switchgear.	\$ 176,438
Pine Grove Elementary	Panels & Transformers	Replace original panels and transformers.	\$ 176,438
Pine Grove Elementary	Paving & Surfacing	Resurface asphalt parking lot.	\$ 229,381
Pine Grove Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	\$ 264,717
Pine Grove Elementary	Fire Alarm Systems	Upgrade fire alarm system.	\$ 308,857
Pine Grove Elementary	Controls	Upgrade control system.	\$ 529,313
Pine Lane Elementary	Flooring	Replace VCT (north building).	\$ 58,250
Pine Lane Elementary	Flooring	Replace VCT with poured acrylic. Abatement (north building).	\$ 162,448
Pine Lane Elementary		Install new IP intercom system for north building.	\$ 264,717
Pine Lane Elementary		Replace south building trough washing stations with sinks (6).	\$ 31,115
Pine Lane Elementary		Replace VCT in kitchen with poured acrylic (south building).	\$ 132,419
		Install new IP intercom system for south building.	\$ 264,717
		Replace RTUs (south building).	\$ 1,764,378
Pioneer Elementary	Flooring	Replace VCT in art room.	\$ 14,593
	Flooring	Replace VCT.	\$ 35,336
Pioneer Elementary		Replace sink countertops with single surface.	\$ 52,943
		Replace playground play pads.	\$ 123,615

Pioneer Elementary	Paving & Surfacing	Resurface asphalt parking lot.	\$	229,381
Pioneer Elementary		Install new IP intercom system for building.	\$	264,717
Pioneer Elementary	Boilers	Replace boiler(s).	\$	441,155
Plum Creek Academy		Install new IP intercom system for building.	\$	132,419
Plum Creek Academy	Fire Alarm Systems	Upgrade fire alarm system.	\$	211,774
Plum Creek Academy	Controls	Upgrade control system.	\$	264,717
Ponderosa High School	Exterior Wall Construction	Recaulk control joints.	\$	17,366
Ponderosa High School	Wash Fountains	Poor condition, need replaced.	\$	40,763
Ponderosa High School	Emergency Light & Power Systems	Replace generator and associated equipment.	\$	132,419
Ponderosa High School	Theater & Stage Equipment	Upgrade lighting and sound systems.	\$	176,438
Ponderosa High School	Chilled Water Systems	Replace cooling tower.	\$	220,577
Ponderosa High School	Intercommunication & Paging System	Install new IP intercom system for building.	\$	441,155
Ponderosa High School	Paving & Surfacing	Resurface asphalt parking lot.	\$	2,646,567
Prairie Crossing Elementary	Flooring	Replace sheet vinyl flooring with MMA.	\$	70,672
Prairie Crossing Elementary	Asphalt Playground	Replace asphalt playground.	\$	123,615
Prairie Crossing Elementary	Chilled Water Systems	Replace cooling tower.	\$	220,577
Prairie Crossing Elementary	Paving & Surfacing	Resurface asphalt parking lot.	\$	229,381
Prairie Crossing Elementary		Install new IP intercom system for building.	\$	264,717
Ranch View Middle School	Sink Countertops	Replace sink counter tops in all restrooms.	\$	74,410
Ranch View Middle School	Flooring	Replace VCT.	\$	88,279
Ranch View Middle School	Flooring	Replace original sheet vinyl flooring with poured acrylic in all restrooms.	\$	88,279
Ranch View Middle School	Emergency Light & Power Systems	Replace generator and associated equipment.	\$	132,419
Ranch View Middle School	Hot Water Service	Replace domestic hot water system, heaters, pumps, and storage.	\$	151,474
Ranch View Middle School	Passenger Elevators	Overhaul elevator.	\$	264,717
Ranch View Middle School		Install new IP intercom system for building.	\$	352,876
Ranch View Middle School	Boilers	Replace boiler(s).	\$	529,313
Ranch View Middle School	Chilled Water Systems	Replace chiller.	\$	529,313
Redstone Elementary	Exterior Wall Construction	Recaulk control joints.	\$	6,995
Redstone Elementary	Exterior Wall Construction	CMU needs sealed. Repair cracks at joints left of main entrance and other areas.	\$	27,014
Redstone Elementary	Sink Countertops	Replace sink countertops with single surface.	\$	39.316
Redstone Elementary	Flooring	Replace VCT.	\$	44,140
Redstone Elementary	Flooring	Replace gym carpet.	\$	70,672
Redstone Elementary	Flooring	Replace poured acrylic flooring in all restrooms.	\$	70,672
Redstone Elementary	Emergency Light & Power Systems	Replace generator and associated equipment.	\$	132,419
Redstone Elementary		Install new IP intercom system for building.	\$	264.717
Redstone Elementary	Carpeting	Replace carpet.	\$	617,593
Renaissance Magnet School	Exterior Wall Construction	Repair cracks in walls.	\$	5,065
Renaissance Magnet School	Sink Countertops	Resurface restroom countertops.	\$	12,663
Renaissance Magnet School		Install new IP intercom system for building.	\$	264,717
Rock Canvon High School	Sink Countertops	Replace sink counter tops in all restrooms.	\$	74,410
Rock Canyon High School	Exterior Wall Construction	Reseal CMU, recaulk control joints.	\$	109,505
Rock Canyon High School	Emergency Light & Power Systems	Replace generator and associated equipment.	\$	132,419
Rock Canyon High School	Flooring	Replace VCT.	\$	132,419
Rock Canyon High School	Flooring	Replace poured acrylic flooring in all restrooms.	\$	132,419
Rock Canyon High School	Theater & Stage Equipment	Upgrade lighting and sound systems.	\$	176,438
Rock Canyon High School		Install new IP intercom system for building.	\$	441,155
Rock Canyon High School	Carpeting	Replace carpet.	\$	1,323,344
	Jourpoung	n topidoo odipot.	Ψ	1,020,044

Rock Canyon High School	Direct Expansion Systems	Replace RTUs.	\$ 4,410,945
Rock Ridge Elementary	Flooring	Replace gym carpet.	\$ 70,672
Rock Ridge Elementary	Flooring	Replace kitchen flooring.	\$ 132,419
Rock Ridge Elementary		Install new IP intercom system for building.	\$ 264,717
Rock Ridge Elementary	Carpeting	Replace carpet.	\$ 617,593
Rocky Heights Middle School	Exterior Wall Construction	Recaulk building control joints.	\$ 17,728
Rocky Heights Middle School	Flooring	Replace sheet vinyl with poured acrylic, some rest rooms complete.	\$ 17,728
Rocky Heights Middle School	Sink Countertops	Replace sink countertops in all restrooms with single surface.	\$ 70,672
Rocky Heights Middle School	Flooring	Replace VCT.	\$ 88,279
Rocky Heights Middle School	Emergency Light & Power Systems	Replace generator and associated equipment.	\$ 132,419
Rocky Heights Middle School	Intercommunication & Paging System	Install new IP intercom system for building.	\$ 352,876
Rocky Heights Middle School	Carpeting	Replace carpet.	\$ 1,261,597
Rocky Heights Middle School	Roof Finishes	Replace .060 EPDM ballasted with .060 fully adhered.	\$ 1,764,378
Roxborough Intermediate	Exterior Wall Construction	Recaulk expansion joints. Reseal CMU.	\$ 29,185
Roxborough Intermediate	Intercommunication & Paging System	Install new IP intercom system for building.	\$ 264,717
Roxborough Intermediate	Fire Alarm Systems	Upgrade fire alarm system.	\$ 370,604
Roxborough Intermediate	Controls	Upgrade control system.	\$ 679,340
Roxborough Primary	Emergency Light & Power Systems	Replace generator and associated equipment.	\$ 132,419
Roxborough Primary	Flooring	Replace kitchen flooring with poured acrylic.	\$ 132,419
Roxborough Primary	Switchgear	Replace main switchgear.	\$ 194,166
Roxborough Primary	Panels & Transformers	Replace original panels and transformers.	\$ 194,166
Roxborough Primary	Intercommunication & Paging System	Install new IP intercom system for building.	\$ 264,717
Roxborough Primary	Fire Alarm Systems	Upgrade fire alarm system.	\$ 282,325
Roxborough Primary	Controls	Upgrade control system.	\$ 529,313
Roxborough Primary	Carpeting	Replace carpet.	\$ 617,593
Saddle Ranch Elementary	Sink Countertops	Replace sink countertops with single surface.	\$ 52,943
Saddle Ranch Elementary	Flooring	Replace epoxy floor with MMA.	\$ 132,419
Saddle Ranch Elementary		Install new IP intercom system for building.	\$ 264,717
Sage Canyon Elementary		Install new IP intercom system for building.	\$ 264,717
Sage Canyon Elementary	Fire Alarm Systems	Upgrade fire alarm system.	\$ 370,604
Sage Canyon Elementary	Controls	Upgrade control system.	\$ 617,593
Sagewood Middle School	Sink Countertops	Replace sink countertops with single surface.	\$ 52,943
Sagewood Middle School	Passenger Elevators	Overhaul elevator.	\$ 264,717
Sagewood Middle School	Intercommunication & Paging System	Install new IP intercom system for building.	\$ 352,876
Sagewood Middle School	Paving & Surfacing	Resurface asphalt parking lot.	\$ 352,876
Sagewood Middle School	Boilers	Replace boiler(s).	\$ 529,313
Sand Creek Elementary	Hot Water Service	Replace domestic water heater and associated piping.	\$ 163,654
Sand Creek Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	\$ 264,717
Sand Creek Elementary	Carpeting	Replace carpet.	\$ 582.257
Sedalia Elementary	Flooring	Replace red ceramic tile in hallway, showing wear and cracks.	\$ 20,261
Sedalia Elementary	Terminal Self-Contained Units	Replace unit heaters at entries.	\$ 77,666
Sedalia Elementary		Install new IP intercom system for building.	\$ 264,717
Sierra Middle School	Sink Countertops	Replace sink countertops as necessary.	\$ 52,099
Sierra Middle School	Flooring	Replace poured acrylic flooring in all restrooms.	\$ 88,279
Sierra Middle School	5	Install new IP intercom system for building.	\$ 352,876
Soaring Hawk Elementary	Exterior Wall Construction	CMU needs sealed.	\$ 22,552
Soaring Hawk Elementary	Flooring	Replace gym carpet.	\$ 70,672

Soaring Hawk Elementary	Flooring	Replace poured acrylic flooring in all restrooms.	\$	70,672
Soaring Hawk Elementary	Emergency Light & Power Systems	Replace generator and associated equipment.	\$	132,419
Soaring Hawk Elementary		Install new IP intercom system for building.	\$	264,717
Soaring Hawk Elementary	Carpeting	Replace carpet.	\$	617,593
South Ridge Elementary	Switchgear	Replace main switchgear.	\$	176,438
South Ridge Elementary	Panels & Transformers	Replace panels and transformers not yet replaced.	\$	176,438
South Ridge Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	\$	264,717
South Ridge Elementary	Fire Alarm Systems	Upgrade fire alarm system.	\$	264,717
Stone Mountain Elementary	Exterior Wall Construction	Recaulk expansion joints. Reseal CMU.	\$	29,185
Stone Mountain Elementary		Install new IP intercom system for building.	\$	264,717
Stone Mountain Elementary	Fire Alarm Systems	Upgrade fire alarm system.	\$	370,604
Stone Mountain Elementary	Controls	Upgrade control system.	\$	679,340
Summit View Elementary	Flooring	Replace VCT flooring in staff restrooms.	\$	3,377
Summit View Elementary	Switchgear	Replace main switchgear.	\$	58,250
Summit View Elementary	Panels & Transformers	Replace original panels and transformers.	\$	194,166
Summit View Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	\$	264,717
Summit View Elementary	Fire Alarm Systems	Upgrade fire alarm system.	\$	344,072
Summit View Elementary	Controls	Upgrade control system.	\$	529,313
Summit View Elementary	Carpeting	Replace carpet.	\$	617,593
Teddy Lane	Direct Expansion Systems	Replace RTU.	\$	441,155
ThunderRidge High School	Theater & Stage Equipment	Small stage curtains are torn and need replaced on one side. Replace cracked seats in auditorium.	\$	32,803
ThunderRidge High School	Exterior Wall Construction	Recaulk control joints. Re-seal CMU.	\$	103,113
ThunderRidge High School	Theater & Stage Equipment	Upgrade lighting and sound systems.	\$	176,438
ThunderRidge High School	Intercommunication & Paging System	Install new IP intercom system for building.	\$	264,717
ThunderRidge High School	Boilers	Replace boiler(s).	\$	705,751
ThunderRidge High School	Paving & Surfacing	Resurface asphalt parking lot.	\$	2,646,567
Timber Trail Elementary	Flooring	Replace VCT.	\$	35,336
Timber Trail Elementary	Sink Countertops	Replace sink countertops with single surface.	\$	52,943
Timber Trail Elementary	Flooring	Replace gym carpet with sport flooring.	\$	70,672
Timber Trail Elementary	Flooring	Replace poured acrylic flooring in all restrooms.	\$	70,672
Timber Trail Elementary	Emergency Light & Power Systems	Replace generator and associated equipment.	\$	132,419
Timber Trail Elementary	Paving & Surfacing	Resurface asphalt parking lot.	\$	141,223
Timber Trail Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	\$	264,717
Timber Trail Elementary	Carpeting	Replace carpet.	\$	582,257
Trailblazer Elementary	Flooring	Replace VCT.	\$	35,336
Trailblazer Elementary	Flooring	Replace kitchen flooring with poured acrylic. Currently Hubelite material (Red).	\$	132,419
Trailblazer Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	\$	264,717
Wildcat Mountain Elementary	Flooring	Replace VCT in classrooms due to building movement.	\$	18,090
Wildcat Mountain Elementary	Flooring	Replace VCT.	\$	35,336
Wildcat Mountain Elementary	Flooring	Flooring Kitchen. Needs-Replace kitchen flooring.	\$	132,419
Wildcat Mountain Elementary	Intercommunication & Paging System	Install new IP intercom system for building.	\$	264,717
Wildcat Mountain Elementary	Boilers	Replace boiler(s).	\$	441,155
Wildcat Mountain Elementary	Chilled Water Systems	Replace chiller.	\$	529,313
CAPITAL RENEWAL & REPLACEMENT: DISTRICT EDUCATIONAL FACILITIES TOTAL: \$				